FINAL REPORT

Radiological Recovery Requirements, Structures, and Operations Research

Volume III,

Decontamination

Analysis of Selected Sites

and Facilities in San Jose, California



CLEARINCHOUSE
FOR PEDERAL SCIENTIFIC AND
TECHNICAL INFORMATION

Hardcopy Micrefishe


\$ 6.00 \$ 1.25 244 \$. M. Walker

PREPARED FOR THE
OFFICE OF CIVIL DEFENSE | ADDITIVE GODY
DEPARTMENT OF THE ARMS
WASHINGTON, D. C. 20310
OCD WORK UNIT NO. 3233B

UNDER

TECHNICAL MANAGEMENT OFFICE
U. S. NAVAL RADIOLOGICAL DEFENSE LABORATORY
SAN FRANCISCO, CALIFORNIA 94135
CONTRACT N228 (62479)-68153
RTT PROJECT QU-214

6 June 1966



THE RESEARCH TRIANGLE INSTITUTE
Operations Research and Economics Division

OCD Review Notice

This report has been reviewed in the Office of Civil Defense and approved for publication. Approval does not signify that the contents necessarily reflect the views and policies of the Office of Civil Defense.

FINAL REPORT: Volume III,

Decontamination Analysis of Selected Sites and Facilities in San Jose, California

Radiological Recovery Requirements, Structures, and Operations Research

by S. M. Walker

Prepared for the Office of Civil Defense Department of the Army Washington, D. C. 20310 OCD Work Unit No. 3233B

under

6 June 1966

Technical Management Office U. S. Naval Radiological Defense Laboratory San Francisco, California 94135 Contract N228(62479)-68153 RTI Project OU-214

Distribution of this document is unlimited.

FINAL REPORT: VOLUME III, Decontamination Analysis of Selected Sites and Facilities in San Jose, California

Radiological Recovery Requirements, Structures, and Operations Research

Prepared for the

Office of Civil Defense

Department of the Army

Washington, D. C. 20310

OCD Work Unit No. 3233B

under

Technical Management Office

U. S. Naval Radiological Defense Laboratory

San Francisco, California 94135

Contract N228(62479)-68153

RTI Project OU-214

by

S. M. Walker

THE RESEARCH TRIANGLE INSTITUTE Operations Research and Economics Division Post Office Box 490 Durham, North Carolina

A. Parsons

Robert S. Titchen

Deputy Director

6 June 1966

PREFACE

The conclusions given in this report are based upon the "Engineering Manual (PM100-1)" method for calculation of "protection factors". Since an error analysis is not presently available, the conclusions should be regarded as tentative, pending the development of such an analysis. In addition, a redistribution of fallout and/or changes in the \gamma-ray spectrum emitted by the fallout may introduce further uncertainties into these conclusions.

ACKNOWLEDGEMENTS

The author is pleased to acknowledge the helpful cooperation of A. Russell Lunsford, Deputy Director, San Jose Department of Civil Defense, and the staff in scheduling and participating in the field surveys which were necessary to conduct this study. Appreciation is also extended to Philip McGill and Philip Rasberry for their valuable assistance in obtaining data and photographs in San Jose.

ABSTRACT

This is Volume III of four separately bound volumes that report the research completed under the general terms of the Office of Civil Defense Subtask No. 32333, "Radiological Recovery Requirements, Structures, and Operations Research". This volume contains the supporting data related to decontamination analyses of sixteen sites and facilities from San Jose, California. Volume I describes the general aspects of the investigations and presents the conclusions and recommendations.

TABLE OF CONTENTS

	PREFA	ACE	iii
	ACKNO	OWLEDGEMENTS	iv
	ABST	RACT	v
	LIST	OF TABLES	xiv
	LIST	OF FIGURES ×	xii
I,	INTRO	ODUCTION	1
	A.	Objectives	1
	В.	Approach	1
	С.	Contents	3
II.		NTAMINATION ANALYSIS OF CALIFORNIA PACKING CORPORATION T NO. 51	7
	Α.	Discussion	7
	В.	Definition of Activities	13
	C.	Protection Factors	14
	D.	Contaminated Planes	14
	E.	Contribution to Intensity Factors (C _{ij} Values)	15
	F.	Relative Intensity Contributions (CF values)	17
	G.	Cost and Effectiveness	18
	Н.	RN Values	19
	I.	RNA Values	20
	J.	Conclusicas	20
III.	DECO	NTAMINATION ANALYSIS OF CALIFORNIA PHARMACEUTICAL LABORATORY	21
	A.	Discussion	21
	В.	Definition of Activities	21
	C.	Protection Factors	25
	D ,	Contaminated Planes	25
	E.	Contribution to Intensity Factors (Cij Values	26

			rage
	F.	Relative Intensity Contributions (CF _{ij} Values)	27
	G.	Cost and Effectiveness	28
	н.	RN Values	28
	I.	RNA Values	29
	J.	Conclusions	29
IV.		ONTAMINATION OF PACIFIC TELEPHONE AND TELEGRAPH COMPANY, JOSE, CALIFORNIA	31
	A.	Discussion	31
	В.	Definition of Activities	37
	С.	Protection Factors	38
	D.	Contaminated Planes	38
	E.	Contribution to Intensity Factors (C Values)	39
	F.	Relative Intensity Contributions (CF ij Values)	40
	G.	Cost and Effectiveness	41
	н.	RN Values	42
	I.	RNA Values	43
	J.	Conclusions	44
v.	DEC	ONTAMINATION OF DOLE CORPORATION WAREHOUSE	45
	Α.	Discussion	45
	В.	Definition of Activities	45
	C.	Protection Factors	51
	D.	Contaminated Planes	52
	E.	Contribution to Intensity Factors (Cij Values)	52
	F.	Relative Intensity Contributions (CF values)	54
	c.	Cost and Effectiveness	55
	н.	RN, Values	56
	ı.	RNA Values	57
	J.	Conclusions	57

			Page
VI.	DECC	ONTAMINATION ANALYSIS OF SAN JOSE MERCURY - NEWS	59
	A.	Discussion	59
	в.	Definition of Activities	59
	c.	Protection Factors	67
	D.	Contaminated Planes	68
	E.	Contribution to Intensity Faccors (Cij Values)	68
	F.	Relative Intensity Contributions (CF; Values)	69
	G.	Cost and Effectiveness	70
	н.	RN Values	71
	I.	RN Values	72
	J.	Conclusions	72
VII.	DEC	ONTAMINATION ANALYSIS OF WESTERN GREYNOUND BUS LINES DEPOT	75
	Α.	Discussion	75
	В.	Definition of Activities	75
	c.	Protection Factors	81
	D.	Contaminated Planes	82
	E.	Contribution to Intensity Factors (C Values)	82
	F.	Relative Intensity Contributions (CF Values)	8
	G.	Cost and Effectiveness	84
	н.	RN Values	84
	I.	RN Values	85
	J.	Conclusion	8
VIII.	DEC	ONTAMINATION ANALYSIS OF SAN JOSE CITY LINES	87
	A.	Discussion	8
	В.	Definition of Activities	8
	C	Protection Factors	93

viii

			Page
	D.	Contaminated Planes	95
	Ε.	Contribution to Intensity Factors (Cij Values)	95
	F.	Relative Intensity Contributions (CF Values)	96
	G.	Cost and Effectiveness	97
	н.	RN Values	97
	I.	RNA Values	98
	J.	Conclusions	98
IX.	DEC	ONTAMINATION ANALYSIS OF CITY CORPORATION YARD	101
	Α.	Discussion	101
	В.	Definition of Activities	107
	c.	Protection Factors	108
	٥.	Contaminated Planes	108
	Ε.	Contribution to Intensity Factors (Cij Values)	109
	F.	Relative Intensity Contribution (CF Values)	110
	G.	Cost and Effectiveness	110
	Н.	RNA Values	111
	ı.	RNA Values	111
	J.	Conclusions	112
х.	DEC	ONTAMINATION ANALYSIS OF FIRE STATION NO. 8	113
	A.	Discussion	113
	В.	Definition of Activities	113
	С.	Protection Factors	119
	D.	Contaminated Planes	120
	٤.	Contribution to Intensity Factors (Cg Values)	120
	F.	Relative Intensity Contributions (CF; Values)	1.21
		Corr and Effectiveness	121

			Page
	н.	RN Values	122
	ı.	RNA Values	123
	J.	Conclusions	123
XI.	DEC	ONTAMINATION ANALYSIS OF RADIO STATION KXRX	125
	A.	Discussion	125
	В.	Definition of Activities	125
	c.	Protection Factors	130
-	D.	Contaminated Planes	131
	Ε.	Contribution to Intensity Factors (Cij Values)	131
	F.	Relative Intensity Contributions (CF Values)	132
	G.	Cost and Effectiveness	133
	н.	RN Values	133
	ı.	RNA Values	134
•	J.	Conclusions	134
XII.	DEC	ONTAMINATION ANALYSIS OF OUTDOOR AREAS IN A RESIDENTIAL AREA.	135
	A.	Discussion	135
	В.	Definition of Activities	135
	C.	Protection Factors	140
	D.	Contaminating Planes	140
	E.	Contribution to Intensity Factors (City Values)	141
	F.	Intensity Contributions	141
	G.	Cost and Effectiveness	142
	н.	RN Values	142
	I.	RNA Values	143
	J.	Conclusions	143
KIII.		CONTAMINATION ANALYSIS OF OUTDOOR LOCATIONS IN THE CENTRAL	1 / 5

			Page
	Α.	Discussion	145
	В.	Definition of Activities	145
	c.	Protection Factors	152
	D.	Contaminated Planes	153
	Ε.	Contribution to Intensity Factor (C _{ij} Values)	153
	F.	Relative Intensity Contributions (CF _{ij} Values)	154
	G.	Cost and Effectiveness	155
	н.	RN. Values	156
	I.	RNA Values	156
	J.	Conclusions	157
xiv.	DECO	NTAMINATION ANALYSIS OF SAN JOSE CITY HALL	159
	A.	Discussion	159
	В.	Definition of Activities	159
	c.	Protection Factors	165
	D.	Contaminated Planes	166
	Ε.	Contribution to Intensity Factors (C _{i,j} Values)	166
	F.	Relative Intensity Contributions (CF ij Values)	168
	G.	Cost and Effectiveness	168
	н.	RN Values	169
	I.	RNA Values	170
	J.	Conclusions	170
xv.	DECC	NTAMINATION ANALYSIS OF VALLEY FAIR SHOPPING CENTER	173
	Α.	Discussion	173
	В.	Definition of Activities	173
	С.	Protection Factors	180
	D.	Contaminated Planes	181

			rage
	E.	Contribution to Intensity Factors	181
	F.	Relative Intensity Contributions	182
	G.	Cost and Effectiveness	182
	н.	RN Values	183
	I.	RNA Values	184
	J.	Conclusions	184
XVI.	DEC	ONTAMINATION ANALYSIS OF SAN JOSE HOSPITAL	135
	Α.	Discussion	185
	В.	Definition of Activities	192
	С.	Protection Factors	194
	D.	Contaminated Planes	195
	Ε.	Contribution to Intensity Factors (C Values)	195
	F.	Relative Intensity Contributions (CF ij Values for San Jose Hospital	198
	G.	Cost and Effectiveness	199
	Н.	RN. Values	200
	I.	RNA Values	201
	J.	Conclusions	201
xvII.	DEC	ONTAMINATION ANALYSIS OF THE SEWAGE TREATMENT PLANT	2 03
	A.	Discussion	2 03
	В.	Definition of Activities	210
	c.	Protection Factors	211
	D.	Contaminated Planes	211
	E.	Contribution to Intensity Factors (C Values)	212
	F.	Relative Intensity Contributions (CF Values)	213
	G.	Cost and Effectiveness	214
	н.	RN, Values	2 14

			Page
	I.	RNA Values	215
	J.	Conclusions	215
XVIII.	SUM	MARY AND CONCLUSIONS	217
	REFE	ERENCES	221

LIST OF TABLES

TABLE		PAGE
I	Fraction of Time as Required by Activity F to be Spent at Detector Location j in California Packing Corp. Plant No. 51	13
11	Contribution to Intensity Factors (C Values) for California Packing Corp. Plant No. 51	16
111	Relative Intensity Contributions (CF Values) for California Packing Corp. Plant No. 51	17
IV	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for California Packing Corp. Plant No. 51	18
v	Fraction of Intensity Remaining [1] Values) for	
	Selected Strategies for California Packing Corp.	
	Plant No. 51	19
VI	Activity Reduction Factors (RN Values) for Selected	
	Strategies and all Activity Patterns for California	
	Corp. Plant No. 51	20
VII	Fraction of Time as Required by Activity A_{i} to be	
	Spent at Detector Location j in California Pharmaceutical	
	Laboratory	25
VIII	Contribution to Intensity Factors (C_{ij} Values) for	
	California Pharmaceutical Company	26
IX	Relative Intensity Contributions (CF values) for	
	California Pharmaceutical Laboratory	27
Х	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for California Pharmaceutical	
	Laboratory	28
XI	Fraction of Intensity Remaining (RN_i Values) for Selected	
	Strategies for California Pharmaceutical Laboratory	28
XII	Activity Reduction Factors (RN _A Values) for Selected	
	Strategies and the Activity Patterns for the California	
	Pharmaceutical Laboratory	29

TABLE.		PAGE
XIII	Fraction of Time as Required by Activity A to be Spent at Detector Location j in Pacific Telephone and Telegraph Company	37
XIV	Contribution to Intensity Factors (C Values) for Pacific Telephone and Telegraph Company	39
ΧV	Relative Intensity Contributions (CF Values) to Pacific Telephone and Telegraph Company	40
XVI	Cost and Effectiveness Data for Selected Methods of Decontaminating Surfaces for Pacific Telephone and Telegraph Company	41
XVII	Fraction of Intensity Remaining (RN Values) for Selected Strategies for Pacific Telephone and Telegraph Company	42
XVIII	Activity Reduction Factors (RN _A Values) for Selected Strategies and all Activity Patterns for Pacific Telephone and Telegraph Company	43
XIX	Fraction of Time as Required by Activity A. To be Spent at Detector Location j in Dole Corporation Warehouse	51
XX	Contribution to Intensity Factors (C Values) for Dole Corporation Warehouse	5 3
XXI	Kelative Intensity Contributions (CF Values) for Dole Corporation Warehouse	54
XXII	Cost and Effectiveness Data for Selected Methods of Decontaminating Surfaces for Dole Corporation Warehouse	55
XXIII	Fraction of Intensity Remaining (RN Values) for Selected Strategies for Dole Corporation Warehouse	56
XXIV	Activity Reduction Factors (RN _A Values) for Selected Strategies and All Activity Patterns for Dole Corporation Warehouse	57

TABLE		PAGE
xxv	Fraction of Time as Required by Activity A to be	
	Spent at Detector Location j in San Jose Mercury-News	67
XXVI	Contribution to Intensity Factors (C _{ij} Values) For San Jose Mercury-News	68
XXVII	Relative Intensity Contributions (CF Values) For San Jose Mercury-News	69
XXVIII	Cost and Effectiveness for Selected Methods for Decontaminating San Jose Mercury-News	70
XXIX	Fraction of Intensity Remaining (RN Values) for Selected Strategies for San Jose Mercury-News	71
xxx	Activity Reduction Factors (RN _A Values) for Selected Strategies and all Activity Patterns for San Jose	, 1
	Mercury-News	72
XXXI	Fraction of Time as Required by Activity A to be Spent at Detector Location j in the Western Greyhound Bus Lines Depot	81
XXXII	Contribution to Intensity Factors (C Values) for Westela Greyhound Bus Lines Depot	82
XXXIII	Relative Intensity Contributions (CF Values) for Western Greyhound Bus Lines Depot	83
XXXIV	Cost and Effectiveness Data for Selected Methods of Decontaminating Surfaces for Western Greyhound Bus	03
	Lines Depot	84
XXXV	Fraction of Intensity Remaining (RN Values) for Selected Strategies for Western Greyhound Bus Lines Depot	84
XXXVI	Activity Reduction Factors (RN _A Values) for Selected Strategies and a 1 Activity Patterns for Western	
	Greyhound Bus Lires Depot	85
XXXVII	Fraction of Time &s Required by Activity A to be	
	Spent at Detector Location j in San Jose City Lines	94

TABLE		PAGE
XXXVIII	Contribution to Intensity Factors (C Values) for	
	San Jose City Lines	96
XXXIX	Relative Intensity Contributions (CF $_{f ij}$ Values) for	
	San Jose City Lines	96
XL	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for San Jose City Lines	97
XLI	Fraction of Intensity Remaining (RN Values) for	
	Selected Strategies for San Jose City Lines	97
XLII	Activity Reduction Factors (RNA Values) for Selected	
	Strategies and all Activity Patterns for San Jose City Lines.	98
XLIII	Fraction of Time as Required by Activity A, to be Spent	
	at Detector Location j in City Corporation Yards	107
XLIV	Contribution to Intensity Factors (Ci Values) for	
	City Corporation Yard	109
XLV	Relative Intensity Contributions (CF Values) for	
	City Corporation Yard	110
XLVI	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for City Corporation Yard	111
XLVII	Fraction of Intensity Remaining (RN, Values) for	
	Selected Strategies for City Corporation Yard	111
XLVIII	Activity Reduction Factors (RNA Values) for Selected	
	Strategies and All Activity Patterns for City Corporation	111
XLIX	Fraction of Time as Required by Activity A, to be	
	Spent at Detector Location j in Fire Station No. 8	119
L	Contribution to Intensity Factors (C Values) for	
	Fire Station No. 8	120
LI	Relative Intensity Contributions (CF Values) for	
	Fire Station No. 8	121
LII	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for Fire Station No. 8	121

TABLE		PAGE
LIII	Fraction of Intensity Remaining (RN Values) for	100
	Selected Strategies for Fire Station No. 8	122
LIV	Activity Reduction Factors (RN $_{ m A}$ Values) for	
	Selected Strategies and All Activity Patterns	
	for Fire Station No. 8	123
LV	Fraction of Time as Required by Activity A_i to be	
	Spent at Detector Location j in Radio Station KXRX	130
LVI	Contribution to Intensity Factors (C Values) for	
	Radio Station KXRX	132
LVII	Relative Intensity Contributions (CF Values) for	
	Radio Station KXRX	132
LVIII	Cost and Effectiveness Data for Selected Methods	
	for Decontaminating Surfaces for Radio Station KXRX	133
LIX	Fraction of Intensity Remaining (RN Values) for	
	Selected Strategies for Radio Station KXRX	133
LX	Activity Reduction Factors (RNA Values) for Selected	
	Strategies and all Activity Patterns for Radio	
	Station KXRX	134
LXI	Fraction of Time as Required by Activity A, to be	
	Spent at Detector Locations j in a Residential Area	140
LXII	Contributions to Intensity Factors (C Values)	
	for a Residential Area	141
7 7 7 7 7		
LXIII	Relative Intensity Contributions (CF Values) to a Residential Area	141
		141
LXIV	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for a Residential Area	142
LXV	Fraction of Intensity Remaining (RN, Values) for	
	Selected Strategies for a Residential Area	142
LXVI	Activity Reduction Factors (RNA Values) for	
	Selected Strategies and All Activity Patterns for	
	a Residential Area	143

TABLES		PAGE
LXVII	Fraction of Time as Required by Activity A to be Spent at Detector Location j in the Central Business District	152
LXVIII	Contribution to Intensity Factors (C Values) for Central Business District	154
LXIX	Relative Intensity Contributions (CF ij Values) for Central Business District	154
LXX	Cost and Effectiveness Data for Selected Methods of Decontaminating Surfaces for a Central Business District	155
LXXI	Fraction of Intensity Remaining (RN Values) for Selected Strategies for Central Business District	156
LXXII	Activity Reduction (RN Values) for Selected A Strategies and all Activity Patterns for Central Business District	156
LXXIII	Fraction of Time as Required by Activity A to be Spent at Detector Location j in San Jose City Hall	16 5
LXXIV	Contributions to Intensity Factors (C Values) for San Jose City Hall	167
LXXV	Relative Intensity Contributions (CF Values) for San Jose City Hall	168
LXXVI	Cost and Effectiveness Data for Selected Methods of Decontaminating Surfaces for San Jose City Hall	168
LXXVII	Fraction of Intensity Remaining (RN Values) for Selected Strategies for San Jose City Hall	169
LXXVIII	Activity Reduction (RN $_{ m A}$ Values) for Selected Strategies and all Activity Patterns for San	
TXXJX	Fraction of Time as Required by Activity A to be	170
	Spent at Detector Location j in Valley Fair Shopping Center	180

TABLE		PAGI
LXXX	Contribution to Intensity Factors (Ci j Values) for	
	Valley Fair Shopping Center	181
LXXXI	Relative Intensity Contributions (CF Values) for	
	Valley Fair Shopping Center	1.82
LXXXII	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for Valley Fair Shopping Center	100
• • • • • • • • • • • • • • • • • • • •		182
LXXXIII	Fraction of Intensity Remaining (RN Values) Selected Strategies for Valley Fair Shopping Center	183
LXXXIV		
TWWIA	Activity Reduction Factors (RNA Values) for Selected Strategies and All Activity Patterns for Valley Fair	
	Shopping Center	184
LXXXV	Fraction of Time as Required by Activity A, to be	
	Spent at Detector Location j in San Jose Hospital	19 3
LXXXVI	Contribution to Intensity Factors (C Values) for	
	San Jose Hospital	197
LXXXVII	Relative Intensity Contribution (CF values) for	
	San Jose Hospital	198
LXXXVIII	Cost and Effectiveness Data for Selected Methods of	
	Decontaminating Surfaces for San Jose Hospital	199
LXXXIX	Fraction of Intensity Remaining (RN, Values) for	000
	Selected Strategies for San Jose Hospital	200
ХC	Activity Reduction Factors (RN _A Values) for Selected Strategies and all Activity Patterns for San Jose	
	Hospital	201
XCI	Fraction of Time as Required by Activity A, to be	
	Spent at Detector Location j in the Sewage Treatment Plant	210
XCII	Contribution to Intensity Factors (C _i Values) for the	
	Sewage Treatment Plant	212

TABLE		PAGE
XCIII	Relative Intensity Contributions (CF Values) for the Sewage Treatment Plant	213
XCIV	Cost and Effectiveness Data for Selected Strategies	
	of Decontaminating Surfaces for Sewage Treatment Plant	214
xcv	Fraction of Intensity Remaining (RN, Values) for	
	Selected Strategies for the Sewage Treatment Plant	214
XCVI	Activity Reduction Factors (RNA Values) for Selected	
	Strategies and all Activity Patterns for the Sewage	
	Treatment Plant	215
XCVII	Fraction of Total Intensity to Various Detector	
	Locations Contributed by the Roof of the Facility	218

LIST OF FIGURES

FIGURE		PAGE
1	Location of Selected Sites and Facilities in San Jose, California	4
2	A Map of the Area Around California Packing Corporation Plant No. 51 Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	8
3	View 1 - California Packing Corp. Plant No. 51 - A View of the Building Showing the Parking Area Adjacent to the Building	9
4	View 2 - California Packing Corp. Plant No. 51 - A View of the Enilding Showing the Adjacent Railroad Tracks	ģ
5	View 3 - California Packing Corp. Plant No. 51 - A View Showing the Length of the Building	10
6	View 4 - California Packing Corp. Plant No. 51 - A View Showing the Parking Area and a Rail Siding at the Loading Platform of the Building	10
7	View 5 - California Packing Corp. Plant No. 51 - A View Showing the Rear of Building	11
S	View 6 - California Packing Corp. Plant No. 51 - A Close-up View Showing the Rear of Building and the Surrounding Ground	11
9	A Map of the Area Around California Packing Corporation Plant No. 51 Showing the Locations and Directions of the Photographs Shown in Figures 3 through 8	12
10	A Map of the Area Around California Pharmaceutical Laboratory Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminating Planes	22
11	View 1 - California Pharmaceutical Laboratory - A View Showing the Front and Side of the Building	23
12	View 2 - California Pharmaceutical Laboratory - A View Showing the Laboratory and the Surrounding Area	23
13	A Map of the Area Around California Pharmaceutical Laboratory Showing the Locations and Directions of the Photographs Shown in Figures 11 and 12	24
14	A Map of the Area Around Pacific Telephone and Telegraph Company Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	32
	T 2 MSI III G A	

FIGURE		PAGE
15	View 1 - Pacific Telephone and Telegraph Company - A View Showing the Front and One Side of the Building	33
16	View 2 - Pacific Telephone and Telegraph Company - A View Showing the Back of the Building and the Four Story Section	33
17	View 3 - Pacific Telephone and Telegraph Company - A View Showing the Back of the Building and the Surrounding Parking Areas	34
18	View 4 - Pacific Telephone and Telegraph Company - A View Showing the Vacant Lot on the Street Behind the Building	34
19	View 5 - Pacific Telephone and Telegraph Company - A View Showing the Proportion of Windows in the Eight Story Section of the Building	35
20	View 6 - Pacific Telephone and Telegraph Company - A Closeup View of the Windows in the Eight Story Section	35
21	A Map of the Area Around Pacific Telephone and Telegraph Company Showing the Locations and Directions of the Photographs Shown in Figures 15 through 20	36
22	A Map of the Area Around Dole Corporation Warehouse Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	46
23	View 1 - Dole Corporation Warehouse - A View Showing the Parking Area and the Storage Area at the Rear of the Building	47
24	View 2 - Dole Corporation Warehouse - A Close-up View Showing the Rear Area of the Building	47
25	View 3 - Dole Corporation Warehouse - A View Showing the Rail Siding Along the Warehouse	48
26	View 4 - Dole Corporation Warehouse - A View Showing the Side of the Warehouse and the Dole Box Storage Yard Across the Street.	48
27	View 5 - Dole Corporation Warshouse - A View Showing the Interior of the Warshouse Roof	49
28	View 6 - Dole Corporation Warehouse - A View Showing Prepared Foods Stocked in the Warehouse	49
29	A Map of the Area Around Dole Corporation Warehouse Showing the Locations and Directions of the Photographs Shown in Figures 23 through 28	50

FIGURE		PAGE
30	A Map of the Area Around San Jose Mercury-News Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	60
31	View 1 - San Jose Mercury-News - An Exterior View of the Front of the San Jose Mercury-News	61
32	View 2 - San Jose Mercury-News - A View Showing the Loading Dock at the Rear of the Building	51
33	View 3 - San Jose Mercury-News - A View Showing the Loading Dock and Parking Area at the Rear of the Building	62
34	View 4 - San Jose Mercury-News - A View Showing the Parking Lots and Buildings Across the Street from the Mercury-News	62
35	View 5 - San Jose Mercury-News - A View Showing a Side of the Mercury-News	63
36	View 6 - San Jose Mercury-News - A View Showing the Roof of the Mercury-News Building	63
37	View 7 - San Jose Mercury-News - Another View Showing the Roof of the Mercury-News Building	64
38	View 8 - San Jose Mercury-News - A View of the Type Setting Room	64
39	View 9 - San Jose Mercury-News - A View of the Copy Room	65
40	View 10 - San Jose Mercury-News - A View of the Press Room	65
41	View 11 - A Map of the Area Around San Jose Mercury-News Showing The Locations and Directions of the Photographs Shown in Figures 31 through 40	66
42	A Map of the Area Around Western Greyhound Bus Depot Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	76
43	View 1 - Western Greyhound Bus Depot - A View Showing the Front of the Bus Depot	77
44	View 2 - Western Grayhound Bus Depot - A Front View of the Sus Depot and the Surrounding Area	17
45	View 3 - Western Greyhound Bus Depot - An Aerial View of the Back of the Bus Depot	78
46	View 4 - Western Greyhound Bus Dapot - A View of the Bus Loading	78

FIGURE		PAGE
47	View 5 - Western Greybound Bus Depot - A View of the Back of the Bus Depot from Acress the Street	79
48	View 6 - Western Greyhound Bus Depot - A View of the Waiting Room	79
49	A Map of the Area Around Western Greyhound Bus Depot Showing the Locations and Directions of the Photographs Shown in Figures 43 through 48	80
50	A Map of the Area Around San Jose City Lines Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	88
51	View 1 - San Jose City Lines - A Front View of the San Jose City Lines	89
52	View 2 - San Jose City Lines - A Back View of the San Jose City Lines	89
53	View 3 - San Jose City Lines - A View Showing the Side and the Drive Under Shed	90
54	View 4 - San Jose City Lines - A View Showing the Gas and Oil Station	90
55	View 5 - San Jose City Lines - A View Showing the Bus Parking Area	91
56	View 6 - San Jose City Lines - Another View Showing the Bus Parking Area	91
57	View 7 - San Jose City Lines - A View Showing the Bus Farking Area and the Surrounding Vicinity	92
58	View 8 - San Jose City Lines - An Interior View of the San Jose City Lines Building	92
59	A Map of the Area Around San Jose Caty Lines Showing the Locations and Directions of the Photographs Shown in Figures 51 through 58	93
60	A Map of the Ares Around City Corporation Yard Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	102
61	View 1 - City Corporation Yard - View of Maintenance Building on 6th Street	103
62	View 2 - City Corporation Yard - View of Office	103
63	View 3 - City Corporation Yard - Back View of Maintanance Buidling.	104

FIGURE		PAGE
64	View 4 - City Corporation Yard - View of an Equipment Storage Shed	104
65	View 5 - City Corporation Yard - View of Equipment Kept in Equipment Storage Shed	10 5
66	View 6 - City Corporation Yard - Another View of Equipment Kept in Equipment Storage Shed	105
67	A Map of the Area Around City Corporation Yard Showing the Locations and Directions of the Photographs Shown in Figures 61 through 66	106
68	A Map of the Area Around Fire Station No. 8 Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contmibuting Contaminated Planes	114
69	View 1 - Fire Station No. 8 - A View of the Entrance to the Fire Station	115
70	View 2 - Fire Station No. 8 - A View of the Truck Entrance to the Fire Station	115
71	View 3 - Fire Station No. 8 - A View of the Fire Station and Some of the Surrounding Area	116
72	View 4 - Fire Station No. 8 - A Back View of the Fire Station and the Parking Area	116
73	View 5 - Fire Station No. 8 - A View of the Bank of the Creek Running Alongside of Fire Station	117
74	View 6 - Fire Station No. 8 - A View of Heavy Growth Surrounding Creek Alongside Fire Station	117
75	A Map of the Area Around Fire Station No. 8 Showing the Locations and Direction of the Photographs Shown in Figures 69 through 74	118
7 5	A Map of the Area Around Radio Station KXRX Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	. 2 0
71	View 1 - Radio Station KXRX - A View of the Front of the Radio Station	127
78	View 2 - Radio Station KXRX - A View of the Station Transmission Towers and the Surrounding Area	1 2 7
79	View 3 - Radio Station KXRX - A View Showing the Fallout Shelter Adjoining the Side of the Station	128

FIGURE		PAGE
80	View 4 - Radio Station KXRX - A View Showing the Slopes of Ground from the Radio Station from the Freeway	128
81	A Map of the Area Around Radio Station KXRX Showing the Locations and Directions of the Photographs Shown in Figures 77 through 80	129
82	A Map of the Area Around Residential Area Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	136
83	View 1 - Residential Area - A View Showing a Typical Intersection.	137
84	View 2 - Residential Area - A View Showing a Typical Street	137
85	View 3 - Residential Area - A View Showing a Typical Home	138
8 6	View 4 - Residential Area - A View Showing the Typical Closeness of the Homes	138
87	View 5 - Residential Area - A View Showing a Typical Single Roof	139
88	A Map of the Area Around Main Intersection in San Jose Business District Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	146
89	A Map of the Area Around a Section of the Business District Containing a Parking Lot in San Jose Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	147
90	View ! - Central Business District - A View Along South First Street	148
91	View 2 - Central Business District - A View Looking North on Market Street From th Corner of South Market and West Santa Clara Streets	148
92	View 3 - Central Business District - A View of the Intersection of 2nd Street and Santa Clara	149
93	View 4 - Central Business District - A View Looking Down S. 1st Street	149
94	View 5 - Central Business District - A View Along S. 2nd Street	150
95	View 6 - Central Business District - A View of the Intersection of W. Santa Clara and Market Streets	150
96	View 7 - Central Business District - A View of the Intersection of 1st Street and Santa Clara	151

FIGURE		PAGE
97	View 8 - Central Business District - A View Looking East Along W. Santa Clara Street	151
98	A Map of the Area Around San Jose City Hall Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	160
99	View 1 - San Jose City Hall - A View of the End and Part of the Front of the Building	161
100	View 2 - San Jose City Hall - Another View of the Front of the Building	161
101	View 3 - San Jose City Hall - A View Showing Part of the Back and Part of the Front of the Building	162
102	View 4 - San Jose City Hall - A View Showing the Back of City Hall and the Lawn	16 2
103	View 5 - San Jose City Hall - A View Showing the Front Entrance to the City Hall	163
104	View 6 - San Jose City Hall - A View Showing the Parking Area and Road Leading to the Side of the City Hall	163
105	A Map of the Area Around San Jose City Hall Showing the Locations and Directions of the Photographs Shown in Figures 99 through 104	164
106	A Map of the Area Around Valley Fair Shopping Center Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	174
107	View 1 - Valley Fair Shopping Center - A View of One of the Parking Areas	175
108	View 2 - Valley Fair Shopping Center - A View of Another Parking Area	175
10 9	View 3 - Valley Fair Shopping Center - A View of Part of the Roof of the Shopping Center and the Surrounding Area	176
110	View 4 - Valley Fair Shopping Center - Another View of the Roof of the Shopping Center and the Surrounding Area	176
111	View 5 - Valley Fair Shopping Center - A View from the Roof of Part of the Parking Area	177
112	View 6 - Valley Fair Shopping Center - A View of a Typical	177

FIGURE		PAGE
113	View 7 - Valley Fair Shopping Center - A View of an Open Court in the Shopping Center	178
114	View 8 - Valley Fair Shopping Center - A View of an Open Walkway in the Shopping Center	178
115	A Map of the Area Around Valley Fair Shopping Center Showing the Locations and Directions of the Photographs Shown in Figures 107 through 114	179
116	A Map of the Area Around San Jose Hospita. Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	186
117	View 1 - San Jose Hospital - A View Showing the Rear of the Hospital	187
118	View 2 - San Jose Hospital - A View of the Side of the Hospital Facing N. 14th Street	187
119	View 3 - San Jose Hospital - A View Showing the Front Entrance to the Hospital	188
120	View 4 - San Jose Hospital - A Partial View of the Interior Court of the Hospital	188
121	View 5 - San Jose Hospital - A View Along N. 15th Street	189
122	View 6 - San Jose Hospital - A View from the Top of the Hospital Showing the Surrounding Area	189
123	View 7 - San Jose Hospital - A View of the Hospital Roof	190
124	View 8 - San Jose Hospital - A View of the Hospital Parking Lot	190
125	A Map of the Area Around San Jose Hospital Showing the Locations and Directions of the Photographs Shown in Figures 117 through 124.	191
126	Aerial View of the Sewage Treatment Plant Facility	2 04
127	A Map of the Area Around Sewage Treatment Plant Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes	205
128	View 1 - Sewage Treatment Plant - A View of the Central Control Building and the Adjacent Parking Lot	2 06
129	View 2 - Sewage Treatment Plant - A View of the Central Control Building and the Surrounding Area	2 06
130	View 3 - Sewage Treatment Plant - A View of the Control Panel in the Central Control Building.	2 07

FIGURES		PAGE
131	View 4 - Sewage Treatment Plant - A View of the Pump Well in the Central Control Building	207
132	View 5 - Sewage Treatment Plant - A View of an Underground Tunnel Leading from the Central Control Building	208
133	View 6 - Sewage Treatment Plant - A View of a Fallout Shelter Area in the Central Control Building	208
134	A Map of the Area Around Sewage Treatment Plant Showing the Locations and Directions of the Photographs Shown in Figures	
	128 through 133	209

Decontamination Analysis of Selected Sites and Facilities in San Jose, California

I. INTRODUCTION

A. Objectives

This report presents the results of an analysis of the cost and effectiveness of decontamination of selected sites and facilities in San Jose, California. The purpose of this analysis is to:

- determine the reduction in dose-rate at several detector locations for various strategies of decontamination;
- determine the reduction in dosage to persons performing operations in the activity area; and
- 3. compute cost estimates in time and manpower for practical decontamination operations.

These results can then be used to determine the extent to which decontamination can accelerate a postattack recovery.

B. Approach

The method of analysis in this report is basically the same as that used in Initial Considerations for an Analysis of Decontamination Effectiveness in Municipal Areas, (Ref. 1). $\frac{1}{}$

The two basic assumptions underlying the calculation of all of the decontamination effectiveness data remain:

the intensity at a specified detector location is linearly and independently related to the intensity contributions from the various contaminated planes. That is, if I is the intensity at detector location i, then one may write:

$$I_1 = C_1 + C_2 + \dots + C_{r_1} \tag{1}$$

^{1/} J. T. Ryan, Research Triangle Institute (1965)

- where the C_i 's are the individual contributions from the n contaminated planes which contribute to the intensity at detector location j; and
- the intensity due to the ith contaminated plane is directly proportional to the amount of fallout material on the ith contaminated plane.

Therefore, the intensity at location j after only the k^{th} area is decontaminated, I_i^k , is given in Eq. (2).

$$I_{j}^{k} = I_{j} - F_{k}CF_{k,j}I_{j}$$
 (2)

where I_j is the intensity at location j prior to decontamination of plane k; F_k is the fraction of fallout removed from the kth contaminated plane; and $CF_{k,j}$ is the fraction of the total intensity prior to decontamination at detector j due to contaminated plane k. In other words,

Other parameters and symbols used are:

- 1. RN = the intensity reduction factor. This is the fraction of pre-decontamination dose-rate remaining at detector location j after decontamination has been accomplished.
- 2. RNA = the activity dose reduction factor. This is the fraction of predecontamination dose accumulated by a person performing activity pattern

 A after decontamination has been accomplished.

The values needed to determine the objectives set forth in I.A. were determined by the use of two computer programs. The C_i values were obtained through the use of the program described in Computer Program for Analysis of Building Protection Factors Parts I and II, (Ref. 2). This is a FORTRAN program, based on the latest techniques in fallout radiation shielding, which is designed to accurately describe the doses within real structures. The remaining values were determined through the use of the program described in A Fortran Program for Decontamination Analysis, (Ref. 3). 3/

^{2/} E. L. Hill, T. Johnson, and R. O. Lyday, Jr., Research Triangle Institute, (1965)
3/ C. Dillard and J. Ryan, Research Triangle Institute, (1965)

This program, also written in FORTKAN, is a debugged and tested program for computing the effectiveness parameters used to analyze municipal decontamination. The $C_{\underline{i}}$ values were inputs to the latter program.

Where precise blueprints were unavailable, educated assumptions were made regarding structural characteristics of the facilities. However, it is believed that the assumptions made are realistic, and do not bias the results of the analysis to any appreciable degree.

Because of the above lack of information, it was also necessary at times to assume that fallout shelters were available to personnel at the facilities. These shelters were accordingly given realistic C_{ij} values. Although they are considered as detector locations, their locations are not shown on the figures because their exact positions are not specified.

C. Contents

This report contains the compiled results of an analysis of the application of decontamination efforts to numerous sites and facilities in San Jose, California. Figure 1 shows the location of the sites and facilities considered, and the accompanying legend identifies them.

For each of the activity areas, the intensity reductions at a number of detector locations are determined for various levels of practical decontamination procedures.

Dose reductions for specified activity patterns within the activity area are also shown. In addition, cost data are presented for a number of the studies corresponding to the effectiveness achieved.

Location of Selected Sites ar Facilities in San Jose, California

Figure 1

Legend for Figure 1


- 1. San Jose City Hall
- 2. City Corporation Yard
- 3. Radio Station KXRX
- 4. Fire Station No. 8
- 5. San Jose Hospital
- 6. Central Business District
- 7. San Jose Mercury-News
- 8. Western Greyhound Bus Lines Depot
- 9. Pacific Telephone and Telegraph Company
- 10. California Packing Corporation Plant No. 51
- 11. California Pharmaceutical Labourtory
- 12. San Jose City Lines
- 13. Valley Fair Shopping Center
- 14. Dole Corporation Warehouse
- 15. A Residential Area
- 16. Sewage Treatment Plant

II. DECONTAMINATION ANALYSIS OF CALIFORNIA PACKING CORPORATION PLANT NO. 51

A. <u>Discussion</u>

California Packing Corporation Plant No. 51 is a Delmonte plant engaged in the preparation and packaging of fruit. It is located away from the central business district and very near the Southern Pacific Company Passenger Depot.

Figure 2 is a simplified diagram of the plant, showing the locations of detectors and indicating the locations, sizes, and surface materials of some of the contributing planes of contamination to the activity area. The diagram also indicates the portion of the building that is one story and the portion that is two stories. Figures 3 through 8 are a number of photographs taken around the plant area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 9 is a map indicating the locations and directions of the photographs.



-

A Map of the Area Around California Packing Corporation Plant No. 51 Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 3

View 1 - California Packing Corp.Plant No. 51 -A View of the Building Showing the Parking Area Adjacent to the Building




Figure 4

View 2 - California Packing Corp. Plant No. 51 -A View of the Building Showing the Adjacent Railroad Tracks



Figure 5

View 3 - California Packing Corp. Plant No. 51 - A View Showing the Length of the Building




Figure 6

View 4 - California Packing Corp. Plant No. 51 -A View Showing the Parking Area and a Rail Siding at the Loading Platform of the Building



Figure 7

View 5 - California Packing Corp. Plant No. 51 - A View Showing the Rear of Building





Figure 8

View 6 - California Lacking Corp. Plant No. 51 - A Close-up View Showing the Rear of Building and the Surrounding Ground



A Map of the Area Around California Packing Corporation Plant No. 51 Showing the Locations and Directions of the Photographs Shown in Figures 3 through 8

B. Definition of Activities

Five different activity patterns are considered in this analysis. Eight detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Dried Fruit Grading Area (1st Story)
2	Dried Fruit Packing Area (1st Story)
3	Fruit Bins (1st Story)
4	Fruit Drying Area (2nd Story)
5	Store Room (2nd Story)
6	Work Shop (1st Story)
7	Shipping Department (1st Story)
8	Shelter Area

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table I defines the five activity patterns.

Table I

FRACTION OF TIME AS REQUIRED 3Y ACTIVITY A TO BE SPENT AT

DETECTOR LOCATION j IN CALIFORNIA PACKING CORP. PLANT NO. 51

		Detector Location j						
Activity Pattern A	l Dried Fruit Grading Area	2 Dried Fruit Packing Ares	3 Fruit Bins	Fruit Drying Area	Store Room	6 Work Shop	7 Shipping Department	8 Shelter Area
A	20	.15	.00	.00	.00	.00	.00	. 65
A ₂	.00	.35	. 00	.00	.00	.00	.00	.65
A ₃	.00	.00	.05	. 35	.00	.00	.00	.60
A.,	.00	.00	.00	.00	. 10	.00	.23	.07
۸ ₅	.00	.00	.00	.00	.00	.20	.13	.67

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 2)

Det	tector Location	Original PF
1	Dried Fruit Grading Area	3.2
2	Dried Fruit Packing Area	3.0
3	Fruit Bin	5.7
4	Fruit Drying Area	5. 5
5	Store Room	5.7
6	Work Shop	3.1
7	Shipping Department	5.3
8	Shelter Area	50

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table I)	Equivalent PF
A ₁	8.0
A ₂	7.8
A ₃	12
A ₄	13
A ₅	9.8

D. Contaminated Planes

Identification Number	Description	Area Size (in ft. ²)	Surface Material
1.4	Roof of Cal. Packing Corp. Plant	128,300	Mostly Shingles
18	Other Roofs	77,200	Mostly Shingles
2	Paved Parking	40,000	Asphalt
3	Streets	234,600	Asphalt
4	Lawns, Bare Earth, Fields, etc.	734,9 0 0	Grass & Ground

E. Contribution to Intensity tors (C Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

1. Two Story Section

- a. Exterior Walls
 - (1) Walls facing Bush and White Streets brick and cinder block (77 lb/ft^2) .
 - (2) Wall facing Alameda brick and cinder block (122 lb/ft²).
 - (3) Wall facing San Fernando Street 12" brick (96 lb/ft²).
- b. Floor 12" reinforced concrete (150 1b/ft²).
- c. Roof wood truss and asphalt shingles (10 lb/ft²).
- d. Interior walls
 - (1) Wall parallel to San Fernando Street 12" brick (108 lb/ft²).
 - (2) Wall parallel to Bush Street 8" brick (72 lb/ft²).

2. One Story Section

- a. Exterior Walls
 - (1) Wall facing San Fernando Street brick and cinder block (81 lb/ft²).
 - (2) Wall facing Bush Street brick and cinder block (94 1b/ft²).
 - (3) Wall facing White Street 8" brick (72 lb/ft2).
 - (4) Wall adjacent to two story section included in two story section therefore (0 $1b/ft^2$).
- b. Roof wood truss and asphalt singles (10 lb/ft²).

Table II lists the contribution to intensity factors of the various planes to the selected detector locations.

Table II
CONTRIBUTION TO INTENSITY FACTORS (C_{ij} VALUES)
FOR CALIFORNIA PACKING CORP. PLANT NO. 51

				Detec	Detector Location	ton j			
		De f col	Dried Fwite	3	., Frent f	5	9	_	8
CO	Contaminated Plane i	. <u>5</u> 6	Packing Area	Fruit	Drying Area	Store	Work Shop	Shipping Department	Shelter Area
5	IA Reof of Calif.								
	Corp.	.2934	.2934	.1685	.1685	.1685	.2934	.1685	.0000
18	Other Roofs	0000	0000.	0000	7000.	.0025	.0001	0000	.0000
8	Paved Parking	0000.	0000.	7500.	0100.	.0005	0000	.0012	0000.
~	Streets	.0167	.0298	3000.	.0067	.0032	.0251	.0174	0000
7	Grass & Ground	.0033	0900'	.0005	.0062	.0023	.0026	.0024	0000.

F. Relative Intensity Contributions (CF. Values)

The relative intensity contributions at detector location j from contaminated plane i are given in Table III below.

Table III

RELATIVE INTENSITY CONTRIBUTIONS (CF_{ij} VALUES)

FOR CALIFORNIA PACKING CORP. PLANT NO. 51

		Detector Location j							
	tomi.ated lane i	1 Dried Fruit Grading Area	2 Dried Fruit Packing Area	3 Fruit Bins	4 Fruit Drying Area	5 Store Room		7 Shipping Department	8 Shelter Area
iΑ	Roof of Calif. Packing Corp.	. 94	.89	.96	.92	. 95	.91	.89	1.00
1B	Other Roofs	.00	.00	.00	.00	.01	.00	.00	.00
2	Paved Parking	.00	.00	.03	.01	.00	.00	.01	.00
3	Streets	.05	.09	.00	.04	.02	.08	.09	.00
4	Grass & Ground	.01	.02	.00	.03	.01	.01	.01	.00

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR CALIFORNIA PACKING CORP. PLANT NO. 51

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Pactor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of Building (1A)	.05	4.3	6
Firehosing	В	Other Roofs (1B)	.05	2.6	6
Firehosing	С	Parking Lots (2)	.03	0.4	5
Firehosing	D	Streets (3)	.03	2.7	5
Street Sweeper	E	Parking Lots (2)	.06	8.0	1
Street Sweeper	F	Streets (3)	.06	4.7	1
Grading	G	Ground (4)	.10	176.4	1

II. RN Values

The fraction of intensity remaining for selected strategies of decontamination is given in Table V below.

Table V

FRACTION OF INTENSITY REMAINING (RN VALUES) FOR SELECTED STRATEGIES FOR CALIFORNIA PACKING CORP. PLANT NO. 51

	Detector Location j							
Combined Strategy	l Dried Fruit Grading Area	2 Dried Fruit Packing Area	3 Fruit Bins	4 Fruit Drying Area	5 Store Room	6 Work Shop		8 Shelter Area
A	.11	. 15	.09	. 12	. 10	. 13	. 16	. 05
С	1.00	1.00	.97	.99	1.00	1.00	. 99	1.00
D	. 95	.91	1.00	.96	. 98	. 92	.91	1.00
E	1.00	1.00	.97	. 99	1.00	1.00	.99	1.00
F	.95	.91	1.00	.97	.98	.93	.91	1.00
G	, 99	.98	1.00	.97	. 99	. 99	.99	1.00
A+B	.11	. 15	.09	. 12	.08	. 13	. 16	.05
A+B+C+D	.06	.07	.05	.08	.06	.06	.06	.05
A+B+E+F	.06	.07	.05	.08	.06	.06	.06	.05
A+B+C+D+G	.05	.05	.05	.05	.05	.05	.05	.05

I. RN Values

The activity reduction factors for selected strategies and all activity patterns are given in Table VI.

Table VI

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES AND ALL

ACTIVITY PATTERNS FOR CALIFORNIA PACKING CORP. PLANT NO. 51

Combined Strategy	A ₁	A ₂	A ₃	A ₄	A ₅
A	.12	.14	.11	. 12	13
С	1.00	1.00	.99	1.00	1.00
D	.94	.92	. 97	.94	.93
E	1.00	1.00	. 99	1.00	1.00
F	.94	. 92	. 97	. 95	. 93
G	.99	.99	.98	. 99	.99
A+B	. i2	.14	.11	.12	.13
A+8+C+D	.06	.06	.07	.06	.06
A+B+E+F	.06	.07	.07	.06	.06
A+B+C+D+G	.05	.05	.05	.05	.05

J. Conclusions

Effective decontamination of the California Packing Corporation Plant No. 51 can be achieved by simply firehosing (Strategy A) the roof of the building. The roof offers a minimum of 89% of the intensity contribution to any of the detectors. Decontaminating the roof by method A would leave a maximum of 16% of the original radiation at any detector location. This strategy would require a team of six (6) men working 4.25 hours.

Further, none of the selected activity patterns would receive more than 14% of the original radiation after roof decontamination by method A.

III. DECONTAMINATION ANALYSIS OF CALIFCRNIA PHARMACEUTICAL LABORATORY

A. Discussion

The California Pharmaceutical Laboratory is a small building located near a commercial area, but surrounded on three sides by residential structures.

Figure 16 is simplified diagram of the laboratory, showing the locations of detectors and indicating the locations, sizes, and surface materials of contributing planes of contamination in the activity area. Figures 11 and 12 are two photographs taken around the area showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 13 is a map indicating the locations and directions of the photographs.

B. <u>Definition of Activities</u>

Two activity patterns are considered in this analysis. Two detector locations are used to characterize these activities. These detector locations are as follows:

Detector Location	Description
1	Laboratory
2	Shelter Area

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend to each detector location. Thus, Table VII de ines the two activity patterns.




Figure 10

A Map of the Area Around California Pharmaceutical Laboratory Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially ContributingContaminating Planes



Figure 11

View 1 - California Fharmaceutical Laboratory - A View Showing the Front and Side of the Building




Figure 12

View 2 - California Pharmaceutical Laboratory -A View Showing the Laboratory and the Surrounding Area




Figure 13

A Map or the Area Around California Pharmaceutical Laboratory Showing the Locations and Directions of the Photographs Shown in Figures 11 and 12

Table VII

FRACTION OF TIME AS REQUIRED BY ACTIVITY A, TO BE SPENT AT

DETECTOR LOCATION j IN CALIFORNIA PHARMACEUTICAL LABORATORY

Activity	Detector	Location j
Pattern A i	l Laboratory	2 Shelter Area
A ₁	.33	.67
A ₂	.50	.50

C. <u>Protection Factors</u>

1. Original PF's at Detector Locations (See Figure 10)

Detector Location		Original PF
1	Laboratory	2.2
2	Shelter Area	20

2. Equivalent Protection Factors for the Activity Patterns

Activity Pattern (See Table VII)	Equivalent PF
A ₁	5.4
A ₂	3.9

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface Material
1A	Roof of Lab	1,900	Shingles
1B	Other Roofs	28,900	Shingles
2	Paved Parking	None	*****
3	Streets	25,000	Asphalt
4	Lawns, Bare Earth, Fields, Etc.	244,200	Grass

E. Contribution to Intensity Factors (C1 Values

The following gives the structural characteristics of the laboratory which were required to calculate the contribution to intensity values:

- 1. Exterior Walls
 - a. Front Wall ½" glass (7 lb/ft²)
 - b. Side and back wall 2" wood (5 lb/ft²)
- Interior Partitions 2" wood with openings (4 lb/ft²)
- 3. Roof wooden shingles on rafters (10 lb/ft)

Table VIII lists the contribution to intensity factors of the various planes to the selected detector locations.

Table VIII $\begin{tabular}{llll} \textbf{CONTRIBUTION TO INTENSITY FACTORS (C}_{ij} & \textbf{VALUES) \\ \hline \textbf{FOR CALIFORNIA PHARMACEUTICAL COMPANY} \\ \end{tabular}$

	Detector Location j		
Contaminated Plane i	1 Laboratory	2 Shelter Area	
1A Roof of Lab	.1130	.0500	
1B Other Roofs	.0000	.0000	
2 Paved Parking 3 Streets	.0000	.0000	
3 Streets 4 Grass & Ground	.3179	.0000	

F. Relative Intensity Contributions (CF_{1j} Values)

The relative intensity contributions are given in Table IX below.

Table IX

RELATIVE INTENSITY CONTRIBUTIONS (CF_{1j} VALUES)

FOR CALIFORNIA PHARMACEUTICAL LABORATORY

	Detector Location j		
Contaminated Plane i	1 Laboratory	2 Shelter Area	
1A Roof of Lab	.24	1.00	
lB Other Roofs	.00	.00	
2 Paved Parking	.00	.00	
3 Streets	.07	.00	
4 Grass & Ground	. 69	.00	

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table X

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR CALIFORNIA PHARMACEUTICAL LABORATORY

Method	Identi- fication Symbol	Surface (Suriace Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Building Roof (1A)	.05	0.1	6
Firehos!ng	В	Streets (3)	.03	0.3	5
Vacuumized Sweeper	C	Streats (3)	. 09	0.5	1
Grading	D	Ground (4)	.10	58.4	1

H. RN Values

The fraction of intensity remaining for selected strategies is given in Table XI.

Table XI

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED

STRATEGIES FOR CALIFORNIA PHARMACEUTICAL LABORATORY

	Detector Location j		
Combined Strategy	l Laboratory	2 Shelter Area	
A	.77	.05	
В	. 94	1.00	
D	.38	1.00	
A+B	.70	.05	
A+C+D	.89	. 05	

I. RN Values

The activity reduction factors for selected strategies and the activity patterns are given in Table XII.

Table XII

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES

AND THE ACTIVITY PATTERNS FOR THE CALTFORNIA PHARMACEUTICAL LABORATORY

Combined	Activity Pattern		
Strategy	A ₁	A 2	
A	. 64	. 70	
В	.95	. 94	
D	.49	.44	
A+B	. 59	.64	
A-i-C+D	.08	.08	

J. Conclusions

A minimum of 93% of the radiation intensity to the detectors comes from the roof of the laboratory and the surrounding grass and ground. Table XI shows a combined strategy of A (firebosing the roof), C (vacuumized sweeping the streets), and D (grading the grass and ground) reduces the radiation in the laboratory to 9% of its original intensity. This is a time consuming method of decontamination because the grading would require one man to work 58.40 hours. Thus, the vitalness of the facility would determine if decontamination was justified.

Attention is brought to the fact that decontaminating the ground becomes necessary because it accounts for 69% of the radiation intensity in the laboratory.


IV. DECONTAMINATION OF PACIFIC TELEPHONE AND TELEGRAPH COMPANY, SAN JOSE, CALIFORNIA

A. Discussion

This telephone and telegraph company is located in the central business district of San Jose. Under postattack conditions it could serve as a vital means of communication, and, therefore, is an important facility to consider decontaminating.

Figure 14 is a simplified diagram of the facility, showing the locations of detectors and indicating the locations, sizes, and surface materials of the contributing planes of contamination in the activity area. The diagram also indicates the portion of the building that is eight stories and a basement and the portion that is four stories and a basement.

Figures 15 through 20 are a number of photographs taken around the facility, showing some of the contaminated planes and other features of the area that would influence Lecontamination. Figure 21 is a map indicating the locations and directions of the photographs.



A Map of the Area Around Pacific Telephone and Telegraph Company Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 15

View 1 - Pacific Telephone and Telegraph Company A View Showing the Front and One Side
of the Building




Figure 16

View 2 - Pacific Telephone and Telegraph Company -A View Showing the Back of the Building and the Four Story Section



The state of the s

Figure 17

View 3 - Pacific Telephone and Telegraph Company - A View Showing the Back of the Building and the Surrounding Parking Areas




Figure 18

View 4 - Pacific Telephone and Telegraph Company A View Showing the Vacant Lot on the
Street Behind the Building




Figure 19

View 5 - Pacific Telephone and Telegraph Company A View Showing the Proportion of Windows
in the Eight Story Section of the Building




Figure 20

View 6 - Pacific Telephone and Telegraph Company - A Closeup View of the Windows in the Eight Story Section




Figure 21

A Map of the Area Around Pacific Telephone and Telegraph Company Showing the Locations and Directions of the Photographs Shown in Figures 15 through 20

B. Definition of Activities

five different activity patterns are considered in this analysis. Five detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Long Distance Switchboard (6th Story)
2	Information Switchboard (6th Story)
3	Automatic Exchange Equipment Room (2nd Story)
4	Telegraph Department (3rd Story)
5	Shelter Area (Basement)

The activities are described entirely according to the amount of time an activity pattern requires a person to spend at each of the detector locations. Thus Table XIII defines the five activity patterns.

Table XIII

FRACTION OF TIME AS REQUIRED BY ACTIVITY A TO BE SPENT AT DETECTOR
LOCATION j IN PACIFIC TELEPHONE AND TELEGRAPH COMPANY

	Detector Location j				
Activity Pattern A	Long Distance Switchboard (6th Story)	Information Switchboard (6th Story)	Automatic Exchange Equipment Room (2nd Story)	4 Telegraph Department (3rd Story)	Shelter Area (Basement)
Al	.33	.00	.00	.00	. 67
A ₂	.00	.00	.00	.40	. 60
A ₃	.15	.20	.00	.00	.65
A ₄	.00	.00	.45	.00	. 55
A ₅	.00	. 33	.00	.00	.67

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 14)

Detector Location	Original PF
1 Long Distance Switchboard (6th Story)	23
2 Information Switchboard (6th Story)	23
3 Automatic Exchange Equipment Room (2nd Story)	65
4 Telegraph Department (3rd Story)	53
5 Shelter Area (Basement)	50 00

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table XIII)	Equivalent PF	
A ₁	70	
A ₂	130	
A ₃	66	
A ₄	142	
A ₅	69	

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>
1A	Roof of Pacific T&T	19,800	Tar and Gravel
18	Other Roofs	53,700	Tar and Gravel
2	Paved Parking	152,600	Asphalt
3	Streets	226,900	\sphalt
4	Lawn, Bare Earth, etc.	327,100	Grass, Dirt, Gravel, and Ground

E. Contribution to Intensity Factors (C, Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

1. Exterior Walls

- a. Walls facing San Fernando and Almaden 11" reinforced concrete with 1" marble facing (150 $1b/ft^2$)
- b. Wall facing Vine 20" cinder block and 4" brick (210 lb/ft²)
- c. Wall facing Westminister 8" reinforced concrete and 1" marble facing (110 1b/ft²)

2. Floors

- a. Basement and first floor 8" reinforced concrete (100 lb/ft²)
- b. Upper floors 6" reinforced concrete (75 1b/ft²)
- 3. Roof 6" reinforced concrete with tar and gravel surface (75 $1b/ft^2$)

Table XIV lists the contributions to intensity factors of the various planes to the selected detentor locations.

Table XIV

CONTRIBUTION TO INTENSITY FACTORS (C_{ij} VALUES) FOR PACIFIC TELEPHOJE AND TELEGRAPH COMPANY

gangangan pangangan di salah d	Detector Location j					
Contaminated Plane i	Long Distance Switchboard (6th Story)	2 Information Switchboard (6th Story)	3 Automatic Exchange Equipment Room (2nd Story)	Telegraph Department (3rd Story)	5 Shelter Area (Basement)	
1A Roof of PT&T	.0401	.0401	.0110	.0136	.0000	
1B Other Roofs	.0004	.0005	.0002	.0007	. 0000	
2 Paved Parking	.0010	.0014	.0018	.0016	.0001	
3 Streets	.0007	.0010	.0018	.0024	.0001	
4 Grass and Ground	.0006	.0005	.0006	.0006	. 0000	

F. Relative Intensity Contributions (CF Values)

The relative intensity contributions at detector location j from contaminated plane i are given in Table XV below.

Table XV

RELATIVE INTENSITY CONTRIBUTIONS (CF_{ij} VALUES)

TO PACIFIC TELEPHONE AND TELEGRAPH COMPANY

		Detector Location j						
С	ontaminateó Plane i	Long Distance Switchboard (6th Story)	Information Switchboard (6th Story)	3 Automatic Exchange Equipment Room (2nd Story)	4 Telegraph Department (3rd Story)	5 Shelter Area (Basement)		
1A	Roof of PT&T	. 94	. 92	.71	. 72	.00		
1B	Other Roofs	.01	.01	.01	.04	.00		
2	Paved Parking	.02	.03	. 12	.08	. 50		
3	Streets	.02	.02	.12	.13	. 50		
4	Grass and Ground	.01	.01	.04	.03	.00		

G. Cost an! Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XVI

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR PACIFIC TELEPHONE AND TELEGRAPH COMPANY

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of PT&T (1A)	. 12	0.6	7
Firehosing	Е	Roof of PT&T (1A)	.03	1.5	7
Vacuumized Sweeper	С	Parking Lots (2)	.09	3.1	1
Vacuumized Sweeper	D	Streets (3)	.09	4.5	1
Grading	E	Ground (4)	.10	78.5	1

H. RN Values

The fraction of intensity remaining for selected strategies is given in Table XVII below.

Table XVII

FRACTION OF INTENSITY R. AINING (RN, VALUES) FOR SELECTED

STRATEGIES FOR PACIFIC TELEPHONE AND TELEGRAPH COMPANY

	Detector Location j						
Combined Strategy	Long Distance Switchboard (6th Story)	2 Information Switchboard (6th Story)	Automatic Exchange Equipment Room (2nd Story)	4 Telegraph Department (3rd Story)	5 Shelter Area (Basement)		
A	, 18	.19	. 37	.37	1.00		
В	.09	.11	.31	.30	1.00		
C+D	.96	.95	.79	.81	.09		
£	.99	. 99	.96	.97	1.00		
B+C+D+E	.04	.05	.06	.08	.09		

I. RNA Values

The acitvity reduction factors for selected strategies and all activity patterns are given in Table XVIII.

Table XVIII

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES AND ALL ACTIVITY PATTERNS FOR PACIFIC TELEPHONE AND TELEGRAPH COMPANY

	Activity Pattern						
Combined Strategy	A ₁	A ₂	A ₃	A ₄	A ₅		
A	.18	.38	.19	.38	. 20		
В	.10	.31	.11	. 32	.11		
C+D	.96	.80	.95	.78	. 94		
E	.99	. 97	.99	.97	. 99		
B+C+D+E	.04	.08	. 04	.05	.05		

J. Conclusions

As shown in Table XVII, the combined strategy of B (firehosing roof of P.T. & T., C (vacuumized sweeping parking lots), D (vacuumized sweeping streets), and E (grading the ground) reduces the radiation intensity at any detector location to a maximum of 9% of the original radiation. A combined strategy of B, C, and D would actually produce adequate decontamination, because (as shown in Table XVII) strategy E only reduces the initial radiation at any detector location by a maximum of 3%. Strategy E appears to be a poor strategy lecause it would require one man 78.5 hours to grade the surrounding ground.

It is seen from Table XVIII that a combined strategy of B, C, and D would reduce the radiation for any activity pattern to an acceptable level.

Attention is brought to the fact, as shown in Table XVII, that firehosing the roof of the building at a mass reduction level of .03 (strategy B) rather than at a level of .12 (strategy A) reduces the remaining radiation at the first four detector locations by from 6% to 9% more, yet only requires a team of seven men to work .85 hours longer.

V. DECONTAMINATION OF DOLE CORPORATION WAREHOUSE

A. Discussion


Dole Corporation Warehouse is a building used to store precanned and prepared food for shipment. In a postattack situation this warehouse would very probably be an excellent source for food, and its decontamination would be highly desirable. The warehouse is located in an area which also contains other Dole buildings, including a cannery.

Figure 22 is a simplified diagram of the plant, showing the locations of detectors and indicating the locations, sizes, and surface materials of the contributing planes of contamination to the activity area. Figures 23 through 28 are a number of photographs taken around the plant area showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 29 is a map showing the locations and directions of the photographs.

B. Definition of Activities

Two different activity patterns are considered in this analysis. Five detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Loading Dock
2	Area A in Warehouse
3	Area B in Warehouse
4	Area C in Warehouse
5	Shelter Area



A Map of the Area Around Dole Corporation Warehouse Showing the Locations of vecectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 23

View 1 - Dole Corporation Warehouse A View Showing the Parking Area
and the Storage Area at the Rear
of the Building



Figure 24

View 2 - Dole Corporation Warehouse -A Close-up View Showing the Rear Area of the Building



Figure 25

View 3 - Dole Corporation Warehouse -A View Showing the Rail Siding Along the Warehouse



Figure 26

Yiew 4 - Dole Corporation Warehouse -A View Showing the Side of the Warehouse and the Dole Box Storage Yard Across the Street



Figure 27

View 5 - Dole Corporation Warehouse -A View Showing the Interior of the Warehouse Roof



Figure 28

View 6 - Dole temperation Warehouse -A View Showing Prepared Foods Stocked in the Warehouse




Figure 29

A Map of the Area Around Dole Corporation Warehouse Showing the Locations and Directions of the Photographs Shown in Figures 23 through 28 The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table XIX defines the two activities.

Table XIX

FRACTION OF TIME AS REQUIRED BY ACTIVITY A TO BE SPENT AT DETECTOR LOCATION j IN DOLE CORPORATION WAREHOUSE

Activity		Detector Location j						
Pattern Ai	l Lo a ding Dock	2 Area A in Warehouse	3 Area B in Warehouse	4 Area C in Warehouse	5 Shelter Area			
A ₁	.20	.05	.08	.00	.67			
A ₂	.05	.00	.00	.28	.67			

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 22)

De	tector Location	Original PF
1	Loading Dock	3.3
2	Area A in Warehouse	3.1
3	Area B in Warehouse	3.4
4	Area C in Warehouse	3.1
5	Shelter Area	20

2. Equivalent Protection Factors for ctivity Patterns

Activity Pattern (See Table XIX)	Equivalent PF
A ₁	7.4
A ₂	7.2

D. Contaminated Planes

Identification toumber	Description	Area Size (in ft ²)	Surface <u>Material</u>
1A	Roof of Dole Bldg.	118,200	Asphalt Sheathing*
18	Other Roofs	182,600	Miscellaneous*
2	Paved Parking	38,000	Asphalt
3	Streets	197,100	Asphalt
4	Lawns, Bare Earth, Fields, Etc.	244,100	Mainly Dirt

E. Contribution to Intensity Factors (C_{1j} Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

- 1. Exterior walls 8" reinforced concrete (100 lb/ft²)
- 2. Roof Wooden planks and asphalt sheathing (10 1b/ft²)

Considered as tar and gravel for decontamination purposes.

Table XX lists the contribution to intensity factors of the various planes to the selected detector locations.

		Detector Location j						
		1	2	3	4	5*		
	taminated lane i	Loading Dock	Area A in Warehouse	Area B in Warehouse	Area C in Warehouse	Shelter Area		
1A	Roof of Dole Bldg.	.1517	. 2944	.2419	.2897	.0500		
1B	Other Roofs	.0002	.0010	.0023	. 0008	.0000		
2	Paved Parking	.1296	.0061	.0163	.0044	.0000		
3	Streets	.0226	.0177	. 0294	.0199	.0000		
4	Grass & Ground	.0025	.0028	.0046	.0044	.0000		

^{*} Assumed Values

F. Relative Intensity Contributions (CF values)

The relative intensity contributions are given in Table XXI below.

Table XXI $\begin{tabular}{ll} \textbf{RELATIVE INTENSITY CONTRIBUTIONS (CF}_{ij} & \textbf{VALUES) } \\ & \textbf{FOR DOLE CORPORATION WAREHOUSE} \\ \end{tabular}$

		Detector Location j						
	Contaminated Plane i	l Loading Dock	2 Area A in Warehouse	3 Area B in Warehouse	4 Area C in Warehouse	5 Shelter Area		
1A	Roof of Dole Bldg.	.49	.91	. 82	.91	1.00		
1B	Other Roofs	.00	.00	.01	.00	.00		
2	Paved Parking	. 42	.02	.06	.01	.00		
3	Streets	.07	.05	.10	.06	.00		
4	Grass and Ground	.01	.01	.02	.01	.00		

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XXII

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR DOLE CORPORATION WAREHOUSE

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of Dole Bldg. (1A)	.03	8.6	7
Street Sweeper	В	Parking Lots (2)	.06	0.8	1
Street Sweeper	С	Streets (3)	.03	3.9	1
Vacuumized Sweeper	D	Parking Lots (2)	.09	0.8	1
Vacuumized Sweeper	E	Streets (3)	.09	3.9	1
Grading	F	Ground (4)	.10	58.8	1

H. RN Values

The fraction of intensity remaining for selected strategies is given in Table XXIII below.

Table XXIII

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES FOR DOLE CORPORATION WAREHOUSE

	Detector Location j						
Combined Strategy	l Loading Dock	Area A in Warehouse	3 Area B in Warehouse	4 Area C in Warehouse	5 Shelter Area		
A	.52	.11	. 20	. 12	.03		
В	. 60	. 98	.95	.99	1.00		
С	.93	.95	. 90	.94	1.00		
מ	.62	. 98	.95	.99	1.00		
E	.93	.95	.91	.94	1.00		
F	.99	.99	.99	.99	1.00		
A+B+C	. 05	.04	. 05	.04	.03		

I. RN Values

The activity reduction factors for selected strategies and both activity patterns are given in Table XXIV.

	Activity	Pattern
Combined Strategy	A ₁	A ₂
A	. 29	. 14
В	.81	. 95
С	.94	. 95
ס	.81	, 95
E	.95	. 96
F	.99	. 99
A+B+C	.04	.04

J. Conclusions

With the exception of the loading dock, the roof of the Dole Warehouse is, by far, the plane offering the greatest radiation intensity to the detector locations. However, because of the position of the dock to the paved parking area, the latter provides 42% of the intensity to the loading dock detector.

Combined decontamination strategy, A (firehosing roof of building), B (street sweeping the parking lots), and C (street sweeping the streets) reduces the radiation remaining to a maximum of 5% of its original intensity at any detector location. This combined strategy can be accomplished relatively quickly, with the longest effort required being the decontamination of the roof, 8.55 hours by a team of seven men.

The above strategy would reduce the radiation to 4% of its original intensity for both activity patterns considered.

It should be stated here that the original PF's inside the warehouse could be made much higher simply by stacking the food in an appropriate manner. The interim contents of the warehouse were not used in computing the original PF's.

VI. DECONTAMINATION ANALYSIS OF SAN JOSE MERCURY - NEWS

A. Discussion


The San Jose Mercury - News Company is a newspaper publishing and printing company located in the business district of San Jose. In a postattack environment, it could be of great benefit in keeping the surrounding community in contact with the state of conditions and affairs.

Figure 30 is a simplified diagram of the building, showing the locations of detectors and indicating the locations, sizes, and surface materials of the contributing planes of contamination to the activity area. The diagram also indicates which portion of the building is two stories and which portion is one story. Figures 31 through 40 are a number of photographs taken around the plant area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 41 is a map showing the locations and directions of the photographs.

B. Definition of Activities

Four different activity patterns are considered in this analysis. Five detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
ĭ	Truck Loading Dock (1st Story)
2	Press Room (1st Story)
3	Copy Room (1st Story)
4	Type Setting Room (2nd Story)
5	Shelter Area






Figure 30

A Map of the Area Around San Jose Mercury-News Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Conteminated Planes




Figure 31

View 1 - San Jose Mercury - News An Exterior View of the Front of the
San Jose Mercury - News



Figure 32

View 2 - San Jose Mercury - News -A View Showing the Loading Dock at the Rear of the Suilding




Figure 33

View 3 - San Jose Mercury - News A View Showing the Loading Dock
and Parking Area at the Rear of
the Building



Figure 34

View 4 - San Jose Mercury - News A View Showing the Parking Lots and
Buildings Across the Street from the
Mercury - News



Figure 35

View 5 - San Jose Mercury - News -A View Showing a **Side** of the Mercury - News Building




Figure 36

View n - San Jose Mercury - News -A View Showing the Roof of the Mercury - News Building



Figure 37

View 7 San Jose Mercury - News Another View Showing the Roof of the
Mercury - News Building



Figure 38

View 8 - San Jose Mercury - News - A View of the Type Setting Room



Figure 39

View 9 - San Jose Mercury - News - A View of the Copy Room




Figure 40

View 10 - San Jose Mercury - News - A View of the Press Room




Figure 41

A Map of the Area Around San Jose Mercury-News Showing the Locations and Directions of the Photographs Shown in Figures 31 through 40

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table XXV defines the four activity patterns.

Table XXV

FRACTION OF TIME AS REQUIRED BY ACTIVITY A TO BE SPENT AT

DETECTOR LOCATION j IN SAN JOSE MERCURY - NEWS

		Detector Location j						
Activity A _i	l Trucking Loading Dock	2 Press Room	3 Copy Room	4 Type Setting Room	5 Shelter Area			
A ₁	.00	.00	.00	.33	.67			
A ₂	.00	.20	.00	.13	.67			
A_3	.10	.23	.00	.00	.67			
A ₄	.00	.00	.33	.00	.67			

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 30)

<u>De</u>	tector Location	Original PF
1	Truck Loading Dock	5.0
2	Press Room	4.0
3	Copy Room	3.3
4	Type Setting Room	5.3
5	Shelter Area	50

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table XXV)	Equivalent PF
A ₁	13
A ₂	11
A ₃	11
A ₄	8.7

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>	
1 A	Roof of Mercury News	49,300	Asphalt Sheathing*	
1B	Other Roofs	188,700	Miscellaneous*	
2	Paved Parking	257,000	Asphalt	
3	Streets	290,100	Asphalt	
4	Lawns, Bare Earth, Fields, Etc.	None		

E. Contribution to Intensity Factors (C, Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

- 1. Exterior walls 8" cinder block (72 lb/ft²)
- 2. Interior walls 6" cinder block (55 1b/ft²)
- 3. Floors 3" reinforced concrete (37 lb/ft²)
- 4. Roof Asphalt sheathing on timber (10 1b/ft²)

Table XXVI lists the contribution to intensity factors of the various planes to the selected detector locations.

Table XXVI

CONTRIBUTION TO INTENSITY FACTORS (C VALUES)

FOR SAN JOSE MERCURY - NEWS

		Detector Location j				
	Contaminated Plane i	l Truck Loading Dock	2 Press Room	3 Copy Room	4 Type Setting Room	5 Shelter Area
14	Roof of Mercury News	.1230	.1230	. 3000	. 1230	. 0200
1B	Other Roofs	.0000	.0000	.0012	.0000	.0000
2	Paved Parking	. 0504	.0131	.0011	.0269	. 0000
3	Streets	.0260	.1137	.0045	.0389	.0000
4	Grass & Ground	.0000	. 0000	.0000	. 0000	. 00 00

^{*} Considered tar and gravel for decontamination purposes.

^{**}Assumed Values

F. Relative Intensity Contributions (CF₁ Values)

The relative intensity contributions are given in Table XXVII below.

Table XXVII

RELATIVE INTENSITY CONTRIBUTIONS (CF_{ij} VALUES)

FOR SAN JOSE MERCURY - NEWS

		Detector Location j				
Contaminated Plane i	l Truck Loading Dock	2 Press Room	3 Copy Room	4 Type Setting Room	5 Shelter Area	
lA Roof of Mercury News	. 62	.49	.98	. 65	1.00	
1B Other Roofs	.00	.00	.00	.00	.00	
2 Paved Parking	.25	.05	.00	.14	.00	
3 Streets	.13	.46	.01	.21	.00	
4 Grass & Ground	.00	.00	.00	.00	.00	

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XXVIII

COST AND EFFECTIVENESS FOR SELECTED METHODS OF DECONTAMINATING SAN JOSE MERCURY - NEWS

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of Mercury News (1A)	.03	3.5	7
Firehosing	В	Roof of Mercury News (1A)	.12	1.5	7
Firehosing	С	Other Roofs (1B)	.03	13.9	7
Firehosing	D	Other Roofs (1B)	.12	8.3	7
Street Sweeper	E	Paved Parking(2)	.06	5.2	1
Street Sweeper	F	Streets (3)	.06	5.8	1

H. RN Values

The fraction of intensity remaining for selected strategies of decontamination is given is Table XXIX below.

Table XXIX

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES FOR SAN JOSE MERCURY - NEWS

Detector Location j					
Combined Strategy	l Truck Loading Dock	2 Press Room	Copy Room	4 Type Setting Room	5 Shelter Area
A	.40	. 52	. 05	.37	.03
В	.46	.57	. 14	.43	. 12
E	.76	.95	1.00	.87	1.00
F	.88	.57	.99	.81	1.00
A+C	.40	.52	.05	. 37	.03
B+D	.46	.57	.14	.43	. 12
E+F	. 64	. 52	.98	. 67	1.00
A+C+E+F	.04	.05	.03	.04	.03

I. RN Values

The activity reduction factors for selected strategies and all activity patterns is given in Table XXX.

Table XXX

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES

AND ALL ACTIVITY PATTERNS FOR SAN JOSE MERCURY - NEWS

	Activity Pattern				
Combined Strategy	A ₁	A ₂	A ₃	A ₄	
A	.31	.40	.42	.05	
В	. 37	.46	. 48	.14	
E	.89	.93	. 92	1.00	
F	.84	.70	. 70	.99	
A+C	.31	.40	. 42	.05	
B+D	. 37	.46	. 48	. 13	
E+F	.73	. 64	. 62	. 98	
A+C+E+F	.04	.04	.04	.03	

J. Conclusions

Table XXIX indicates that the combined strategy A (firehosing the roof), C (firehosing other roofs), E (street sweeping parking lots), and F (street sweeping streets) will reduce the radiation remaining at any detector location to a maximum of 5% of its original value. A scrategy of B (firehosing the roof), D (firehosing other roofs), E (street sweeping paved parking), and F (street aweeping streets), might also be employed, but the fraction of intensity remaining would be slightly higher because B and D have a mass reduction factor of .12, while A and C have a mass reduction factor of .03.

Attention is brought to comparing strategy A with B and C with D in Table XXVIII

as a way of showing the different amount of effort to decontaminate the same plane by the same means at different levels of mass reduction.

If combined strategy A+C+E+F is employed, no activity pattern will receive more than 4% of the original radiation.

VII. DECONTAMINATION ANALYSIS OF WESTERN GREYHOUND BUS LINES DEPOT

A. Discussion

The Western Greyhound Bus Lines Depot is located in the business district of San Jose.

Figure 42 is simplified diagram of the depot showing the locations of detectors and indicating the locations, sizes, and surface materials of the contributing planes of contamination to the activity area. Figures 43 through 48 are a number of photographs taken around the depot showing many of the contaminated planes and other features of the area that influence decentamination. Figure 49 is a map showing the locations and directions of these photographs.

B. Definition of Activities

Three different activity patterns are considered in this analysis. Five detector locations are required to characterize the activities. These detector locations are as follows:

Detector Location	Description
1	Ticket Counter
2	Baggage Room
3	Main Lobby
4	Loading Area
5	Shelter Area




Figure 42

A Map of the Area Around Western Greyhound Bus Depot Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes




Figure 43

View 1 - Western Greyhound Bus Depot -A View Showing the Front of the Bus Depot



Figure 44

View 2 - Western Greyhound Bus Depot -A Front View of the Bus Depot and the Surrounding Area



Figure 45

View 3 - Western Greyhound Bus Depot --An Aerial View of the Back of the Bus Depot



Figure 46

View 4 - Western Greyhound Bus Depot -A View of the Bus Loading Area



Figure 47

View 5 - Western Greyhound Bus Depot A View of the Back of the Bus Depot
from Across the Street



Figure 48

View 6-Western Greyhound Bus Depot -A View of the Waiting Room




Figure 49

A Map of the Area Around Western Greyhound Bus Depot Showing the Locations and Directions of the Photographs Shown in Figures 43 through 48

The activities are 'scribed entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations.

Thus, Table XXXI defines the three activity patterns.

Table XXXI

FRACTION OF TIME AS REQUIRED BY ACTIVITY A TO BE SPENT AT DETECTOR LOCATION j IN THE WESTERN GREYHOUND BUS LINES DEPOT

		Dete	ctor Loca	tion j	
Activity Pattern ^A i	1 Ticket Counter	2 Baggage Room	3 Main Lobby	4 Loading Area	5 Shelter Area
A ₁	.25	.00	.08	.00	. 67
\mathbf{A}_{2}	.00	.17	.00	.16	.67
A ₃	.00	.05	. 28	.00	.67

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 42)

Detector Location	Original PF
1 Ticket Counter	5.6
2 Baggage Room	5.7
3 Main Lobby	5.6
4 Loading Area	3.2
5 Shelter Area	20

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table XXXI)	Equivalent PF
A ₁	11
A ₂	8.8
A ₃	11

D. Contaminated Planes

Identification Number	Description	Area Size <u>(in ft²)</u>	Surface <u>Material</u>
1A	Roof of Greyhound Depot	19,500	Tar & Gravel
1B	Other Roofs	1.12,200	Tar & Gravel
2	Paved Parking	.50,800	Aspha1t
3	Streets	148,200	Asphalt
4	Lawns, Bare Earth, Fields, Etc.	None	******

E. Contribution to Intensity Factors (C_{ij} Values)

The following gives the structural characteristics of the building which were required to calculate the contributions to intensity values:

- 1. Exterior walls 8" hollow block (55 lb/ft²)
- 2. Interior partitions 6" cinder block (54 lb/ft²)
- 3. Roof cellular deck with tar & gravel covering (40 lb/ft²)

Table XXXII lists the contribution to intensity factors of the various planes to the selected detector locations.

				Detector	Location j	
C	ontaminated Plane i	l Ticket Counter	2 Baggage Room	3 Main Lobby	4 Loading Area	5 Shelter Area
1A	Roof of Grey- hound Depot	. 0985	.0976	. 0945	. 0556	.0500
18	Other Roofs	.0000	.0000	.0000	.0000	.0000
2	Paved Parking	.0398	. 0376	. 0494	. 2427	.0000
3	Streets	.0400	. 0407	. 0340	.0176	.0000
4	Grass & Ground	. 0000	.0000	. 0000	. 0000	.0000

F. Relative Intensity Contributions (CF Values)

The relative intensity contributions are given in Table XXXIII.

Table XXXIII $\begin{tabular}{ll} \textbf{RELATIVE INTENSITY CONTRIBUTIONS (CF}_{ij} & \textbf{VALUES) \\ \hline \textbf{FOR WESTERN GREYHOUND BUS LINES DEPOT} \\ \end{tabular}$

		Detector Location j				
	taminated lane i	1 Ticket Counter	2 Baggage Room	3 Main Lobby	4 Loading Area	5 Shelter Area
1A	Roof of Greybound Depot	. 55	. 35	.53	. 18	1.00
1B	Other Roofs	.00	.00	.00	.00	.00
2	Paved Parking	. 22	.21	.28	.77	.00
3	Streets	. 22	.23	.19	.06	.00
4	Grass & Ground	.00	.00	.00	.00	.00

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XXXIV

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS
OF DECONTAMINATING SURFACES FOR WESTERN
GREYHOUND BUS LINES DEPOT

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (fraction fallout material remaining after dacontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of Greyhound Depot(1A)	.03	1.4	7
Street Sweeper	В	Paved Parking (2)	.06	3.0	1
Street Sweeper	С	Streets (3)	.06	3.0	1

H. <u>RN Values</u>

The frection of intensity remaining for selected strategies of decontamination are given in Table XXXV below.

Table XXXV

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES FOR WESTERN GREYHOUND BUS LINES DEPOT

		Detector Location 1					
Combined Strategy	l Ticket Counter	2 Baggage Room	3 Main Lobby	4 Loading Area	5 Shelter Area		
A	.46	.46	.48	.83	.03		
В	. 79	. 80	76	. 28	1.00		
c	.79	. 78	.82	. 95	1.00		
A+B	. 25	. 26	. 2 2	.11	.03		
A+C	.25	. 24	. 31	. 78	. 6)3		
A+B+C	.04	.04	.04	.05	.03		

I. RN Values

The activity reduction factors for selected strategies and all activity patterns are given in Table XXXVI.

	Act!	Activity Pattern		
Combined Stategy	A ₁	A ₂	A ₃	
A	.31	. 50	. 32	
В	.86	.63	. 84	
С	.87	. 92	. 88	
A+B	.17	. 12	.16	
A+C	.18	. 42	.20	
A+B+C	.04	.04	.04	

J. Conclusions

Table XXXV shows that combined strategy A (firehosing the roof of the bus depot), B (street sweeping the paved parking), and C (street sweeping the streets) will reduce the radiation remaining at any detector location to maximum of 5% of its original value. This decontamination can be accomplished quickly with relatively few people as Table XXXIV indicates. No consideration is given to decontaminating roofs of other buildings, because they contillute no radiation to the detector locations.

Combined strategy A+B+C reduces the radiation for all activity patterns to 4% of the radiation that would have been received originally.

VIII. DECONTAMINATION ANALYSIS OF SAN JOSE CITY LINES

A. Discussion


San Jose City Lines is the bus garage and repairing facility for the local bus line. It is located away from the central business district. In a postattack situation the local bus service might be used to transport people and necessary food, medicipe, etc. to various points in the city.

Figure 50 is a simplified diagram of the facility, showing the locations of detectors and indicating the locations, sizes, and surface materials of the contribut. Planes of contamination to the activity area. Figures 51 through 58 are a number of photographs taken around the building area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 59 is a map showing the locations and directions of the photographs.

B. Definition of Activities

Four different activity patterns are considered in this analysis. Five detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Repair Area A
2	Repair Area B
3	Repair Area C
4	Outdoor Gas & Oil Facility
5	Shelter Area



Paved Streets - 118,200 Square Feet




Figure 50

A Map of the Area Around San Jose City Lines Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 51

View 1 - San Jose City Lines - A Front View of the San Jose City Lines



Figure 52

View 2 - San Jose City Lines - A Back View of the San Jose City Lines




Figure 53

View 3 - San Jose City Lines - A View Showing the Side and the Drive-Inder Shed




Figure 54

View ' - San Jose City Lines - A View Showing the Gas and Oil Station



Figure 55

View 5 - San Jose City Lines - A View Showing the Bus Parking Area



Figure 56

View 6 - San Jose City Lines - Another View Showing the Bus Parking Area



Figure 57

View 7 - San Jose City Lines - A View Showing the Bus Parking Area and the Surrounding Vicinity




Figure 58

View 8 - San Jose City Lines - An Interior View of the San Jose City Lines Building




Figure 59

A Map of the Area Around San Jose City Lines Showing the Locations and Directions of the Photographs Shown in Figures 51 through 58

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations.

Thus, Table XXXVII defines the four activity patterns.

Table XXXVII

FRACTION OF TIME AS REQUIRED BY ACTIVITY A₁ TO BE SPENT AT DETECTOR LOCATION j IN SAN JOSE CITY LINES

	Detector Location j				
Activity A _i	l Repair Area A	2 Repair Area B	3 Repair Area C	4 Outdoor Gas & Oil Facility	5 Shelter Area
A ₁	.30	•00	•05	•00	.65
A ₂	.00	.13	.20	.00	.67
A ₃	.00	.15	.00	.10	.75
A ₄	.00	.00	,35	.00	.65

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 50)

Detector Location	Original PF
l Repair Area A	2.0
2 Repair Area B	1.7
3 Repair Area C	2.0
4 Outdoor Gas & Oil Facili	2 _• 0
5 Shelter Area	20

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table XXXVIII)	Equivalent PF
A ₁	4.9
A ₂	4.8
A ₃	5.7
A ₄	4.9

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>
1A	Roof of City Lines	19,000	Asphalt Sh ea thing
18	Other Roofs	78,200	Shingles
2	Paved Parking	54,700	Asphalt
3	Streets	118,200	Asphalt
4	Lawns, Bare Earth, Fields, etc.	245,000	Grass & Ground

E. Contribution to Intensity Factors (Cij Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

- 1. Exterior Walls 6" hollow concrete block (42 lb/ft²)
- 2. Roof Aspnalt roofing on wooden planks (10 lb/ft²)

Table XXXVIII lists the contribution to intensity factors of the various planes to the selected detector locations.

Table XXXVIII $\begin{tabular}{ll} \textbf{CONTRIBUTION TO INTENSITY FACTORS ($C_{i,j}$ VALUES) FOR SAN JOSE CITY LINES $C_{i,j}$ and $C_{i,j}$ values in the same of the same of$

Detector Location j							
	Contaminated Plane i	l Repair Area A	2 Repair Area B	Repair Area C	4 Outdoor Gas & Oil Facility	5 * Shelter Area	
1A	Roof of City Lines	.3626	.3326	.3453	.0000	.0500	
1в	Other Roofs	.0002	.0001	.0001	.0000	.0000	
2	Paved Parking	.0515	.1919	.0652	.3600	.0000	
3	Streets	.0550	.0309	.0506	.0200	.0000	
4	Grass & Ground	.0261	.0325	.0238	.1300	.0000	

F. Relative Intensity Contributions (CF_{1j} Values)

The relative intensity contributions are given in Table XXXIX.

 $\label{eq:table_XXXIX}$ RELATIVE INTENSITY CONTRIBUTIONS (CF $_{i\,j}$ VALUES) FOR SAN JOSE CITY LINES

Detector Location j						
	Contaminated Plane i	l Repair Area A	2 Repair Area B	3 Repair Arca C	4 Outdoor Gas & Oil Facility	S Shelter [*] Area
1 A	Roof of City Lines	.73	. 57	.70	.00	1.00
18	Other Roofs	.00	.00	.00	.00	.00
2	Paved Parking	.10	.33	.13	. 71	.00
3	Streets	.11	.05	.10	.04	.00
<i>y</i> .	Grass & Ground	.05	.06	.06	. 25	.OG

Assumed Values

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XL

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR SAN JOSE CITY LINES

Method	Idenci- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of City Lines (1A)	.05	0.7	6
Vacuumized Sweeper	В	Parking Lots (2)	.09	1.1	1
Vacuumized Sweeper	C	Streets (3)	.09	2.4	1
Grading	D	Ground (4)	.10	58.1	1

H. RN Values

The fraction of intensity remaining for selected strategies of decontamination are given in Table XLI below.

Table XLI

FRACTION OF INTENSITY REMAINING (RN, VALUES)

FOR SELECTED STRATEGIES FOR SAN JOSE CITY LINES

	Detector Location j						
Combined Strategy	l Repair Area A	2 Repair Area B	3 Repair Area C	4 Outdoor Gas & Oil Facility	5 Shelter Area		
A	. 30	.46	.33	1.00	. 05		
B	91	. 70	. 88	. 36	1.00		
c	.90	. 95	. 91	. 96	1.00		
D	. 95	. 95	. 95	.77	1.30		
8+C	.80	, 66	. 79	.32	1.00		
A+B+C+D	.06	. 57	. მჩ	. 09	.05		

I. RN, Values

The activity reduction factors for selected strategies and all activity patterns are given in Table XLII.

Table XLII

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES

AND ALL ACTIVITY PATTERNS FOR SAN JOSE CITY LINES

		Activity 1		
Combined Strategy	A ₁	A ₂	A ₃	A ₄
A	.27	.33	.53	. 29
В	.92	.83	.67	.90
С	.92	. 94	.97	. 92
D	.96	. 96	.91	. 95
B+C	.83	.77	. 63	.82
A+B+C+D	.06	.06	.07	.06

J. Conclusions

Table XLI shows that the radiation intensity at any detector location can be reduced to a maximum of 9% of its original value by combined strategy A (firehosing roof of building), B (vacummized sweeping parking lots), C (vacummized sweeping streets), and D (grading the ground). If it is not felt vital to decontaminate for detector 4 (the outdoor gas and oil facility), decontamination method A+>+C would be sufficient. This is because the grass and ground contribute only a small amount of the relative intensity to any detector except detector 4. Judgment would have to be used to determine if decontamination of detector 4 is worth one man spending 58.1 hours grading the surrounding ground.


Only activity pattern \mathbf{A}_3 requires a person to be at the outdoor gas and oil

facility. Therefore, this pattern would be the only activity that would not have the radiation reduced appreciably without decontamination method D.

IX. DECONTAMINATION ANALYSIS OF CITY CORPORATION YARD

A. Discussion

The San Jose. City Corporation Yard, which is the maintenance and cleaning equipment depot for the city, occupies a complete city block. Within this area are two equipment storage buildings, a supply warehouse, a box and crate warshouse, a complete maintenance shop, and an office building. Decontamination of this area would be very important to postattack recovery because it is here that the city's street sweepers, flushers, etc. are stored. For this report, detectors were located in the maintenance shop and one of the equipment storage buildings. Figure 60 is a simplified diagram of the yard, showing the locations of the detectors and indicating the locations, sizes, and surface materials of contributing planes of contamination to the activity area. Figures 61 through 66 are a number of photographs taken around the yard area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 67 is a map showing the locations and directions of the photographs.



A Map of the Area Around City Corporation Yard Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 61

View 1 - City Corporation Yard -View of Maintenance Building on 6th Street




Figure 62

View 2 - City Corporation Yard - View of Office



Figure 63

View 3 - City Corporation Yard Back View of Maintenance Building



Figure 64

View 4 - City Corporation Yard -View of an Equipment Storage Shed




Figure 65

View 5 - City Corporation Yard -View of Equipment Kept in Equipment Storage Shed



Figure bb

View 0 - City Corporation Yard Another View of Equipment Kept
in Equipment Storage Shed



A Map of the Area Around City Corporation Yard Showing the Locations and Directions of the Photographs Shown in Figures 61 through 66

B. <u>Definition of Activities</u>

Four different activity patterns are considered in this analysis. Five detector locations are required to characterize the activities. These detector locations are as follows:

Detector Location	Description
1	Equipment Storage
2	Electrical Shop
3	Auto Repair Shop
4	Machine Shop
5	Shelter Area

The activities are described entirely according to the amount of time that the activity pattern requires a person to spend at each of the detector locations. The following table thus defines the four activity patterns:

Table XLIII

FRACTION OF TIME AS REQUIRED BY ACTIVITY A TO BE SPENT AT DETECTOR LOCATION j IN CITY CORPORATION YARDS

		Detecto	r Location	<u> </u>	
Activity Pattern A _i	Equipment Storage	2 Electric Shop	3 Auto Repair	4 Machine Shop	5 Shelter Area
A	. 10	.00	.00	. 23	. 67
A ₂	.00	. 20	.00	. 10	. 70
A ₃	.20	. 00	.15	.00	.65
A4	.00	.10	. 10	. 10	.70

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 60)

Detector Location	Original PF
1 Equipment Storage Bldg.	2 , 48
2 Electrical Shop	3.75
3 Auto Repair Shop	7.19
4 Machine Shop	3.29
5 Shelter Area	20.00

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern-(See Table XLII)	Equivalent PF
A ₁	6. 9 6
A ₂	8.42
A ₃	7.47
A ₄	9.44

D. Concaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface Material
1A	Roof of Equipment Stora and Maintenance Bldgs.	ge 40,400	Corrugated Asbestos*
18	Other Roofs	134,900	Shingles
2	Paved Parking	83,950	Asphalt
3	Streets	264,000	Asphalt
4	Lawns, Bare Earth, Fields, etc.	46,750	Grass

^{*} Assumed shingles for decontamination purposes

E. Contribution to Intensity Factors (C_{ij} Values)

The following gives the structural characteristics of the buildings which were required to calculate the contribution to intensity values:

1. Equipment Storage Building

- a. Exterior end walls ~ 8" cinder block (72 lb/ft²)
- b. Exterior side walls open
- c. Roof 20 galvanized corrugated asbestos (2 lb/ft²)

2. Maintenance Building

- a. Exterior walls 8" cinder block (72 lb/ft²)
- b. Interior partitions 6" cinder block (54 lb/ft²)
- c. Roof corrugated asbestos (4 lb/ft²)

Table XIV lists the contribution to intensity factors of the various planes to the selected detector locations.

Table XLIV

CONTRIBUTION TO INTENSITY FACTORS (City CORPORATION YARD

		Detector Location j				
	amin ated lane i	l Equipment Storage Building	2 Electrical Shop	3 Auto Repair Shop	4 Machine Shop	5 Shelter Area
1 A	Roof of Bldg.	. 1908	. 1963	.0685	. 2324	. 0500
1 B	Other Roofs	. 0000	. 0000	.0000	.0000	.0000
2	Paved Parking	. 2039	.0463	.0460	.0427	. 0000
3	Streets	.0078	.0239	.0244	.0288	. 0000
4	Grass and Ground	. 0000	.0001	.0001	.0001	.0000

F. Relative Intensity Contribution (CF | Values)

The relative intensity contributions are given in Table XLV.

Table XLV

RELATIVE INTENSITY CONTRIBUTIONS (CF_{ij} VALUES)

FOR CITY CORPORATION YARD

	Detector Location j					
Contaminated Plane i	l Equipment Storage Building		3 Auto Repair Shop	4 Machine Shop	5 Shelter Area	
1A Roof of Bldgs.	.47	. 74	. 49	. 76	1.00	
1B Other Roofs	.00	.00	.00	.00	.00	
2 Paved Parking	.51	.17	. 33	.14	.00	
3 Streets	.02	.09	.18	.09	.00	
4 Grass and Ground	.00	.00	.00	.00	.00	

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XLVI

COST AND EFFECTIVENESS LATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR CITY CORPORATION YARD

Method	Identi- fication Symbol	Surface (Surface Humber)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roofs of Equipment Storage & Maintenance Bldgs. (1A)	.07	1.70	7
Vacuumized Sweeper	В	Parking Lots (2)	.09	1.65	1
Vacuumized Sweeper	С	Streets (3)	.0)	5.30	1

H. RNA Values

The fraction of intensity remaining for selected strategies of decontamination are given in Table XLVII below.

Table XLV11

FRACTION OF INTENSITY REMAINING (RN, VALUES)

FOR SELECTED STRATEGIES FOR CITY CORPORATION YARD

	Detector Location j					
Combined Strategy	l Equipment Storage Building	2 Electrical Shop	3 Auto Repair Shop	4 Machine Shop	5 Shelter Area	
A	.56	. 32	.54	.29	.07	
В	.54	. 84	.70	.87	1.00	
С	.98	. 92	.84	.91	1.00	
в+с	.52	.76	. 54	. 79	1.00	
A+B+C	.08	.08	.08	.08	.07	

I. RN Values

The activity reduction factors for selected strategies and all activity patterns are given in Table XLVIII.

Table XLVIII

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES

AND ALL ACTIVITY PATTERNS FOR CITY CORPORATION YARD

	Activity Pattern			
Combined Strategy	A ₁	A ₂	A ₃	A ₄
A	.31	.24	. 44	. 26
ь	.81	. 90	. 68	.88
С	. 95	. 94	. 96	. 93
в+с	.76	. 84	. 64	. 82
A+B+C	.08	.07	.08	.07

J. Conclusions

The roofs of other buildings and the surrounding grass and ground do not offer any relative intensity contributions to the detector locations. Therefore, it is unnecessary to consider decontaminating these planes.

Table XLVII and XLVIII show that the combined decontamination strategy A (fire-hosing roofs of equipment storage and maintenance buildings), B (vacuumized sweeping parking lots), and C (vacuumized sweeping of streets) would reduce the fraction of intensity remaining at any detector location or for any activity pattern to a maximum of 8%.

Further, Table XLVI shows the above strategy can be accomplished in a relatively short time with a maximum of nine men.

X. DECONTAMINATION ANALYSIS OF FIRE STATION NO. 8

A. Discussion

Fire Station No. 8 is located in a surburban area of San Jose. In a postattack situation the station's continual operation could be of considerable value to the community.

Figure 68 is a simplified diagram of the station, showing the locations of detectors and indicating the locations, sizes and surface materials of the contributing planes of contamination to the activity area. Figures 69 through 74 are a number of photographs taken around the station area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 75 is a map showing the locations and directions of the photographs.

B. Definition of Activities

Three different activity patterns are considered in this analysis. Three detector locations are used to characterize these activity patterns. The detector locations are as follows:

Detector Location	Description
1	Equipment Storage Area
2	Alarm Switchboard
3	Shelter Area




Figure 68

A Map of the Area Around Fire Station No. 8 Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes




Figure 69

View 1 - Fire Station No. 8 -A View of the Entrance to the Fire Station




Figure ?0

View 2 - Fire Station No. 8 -A View of the Truck Entrance to the Fire Station



Figure 71

View 3 - Fire Station No. 8 A View of the Fire Station and
Some of the Surrounding Area



Figure 72

View 4 - Fire Station No. 8 -A Back View of the Fire Station and the Parking Area



Figure 73

View 5 - Fire Station No. 8 A View of the Bank of the Creek
Running Alongside of the Fire Station



Figure 74

View 6 - Fire Station No. 8 A View of Heavy Growth Surrounding the
Creek Alongstile the Fire Station




Figure 75

A Map of the Area Around Fire Station No. 8 Showing the Locations and Directions of the Photographs Shown in Figures 69 through 74

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table XLIX defines the three activity patterns.

Table XLIX

FRACTION OF TIME AS REQUIRED BY ACTIVITY A

TO BE SPENT AT DETECTOR LOCATION j IN FIRE STATION NO. 8

		Detector Location j		
Activity A ₁	1 Equipment Storage Area	2 Alarm Switchboard	3 Shelter Area	
A ₁	.35	.00	.65	
A ₂	.10	.20	. 70	
A ₃	.00	.40	. 60	

C. Protection Factors

1. Original PT's at Detector Locations (See Figure 68)

De	etector Location	Original PF
1	Equipment Storage Area	5.5
2	Alarm Switch	9.2
3	Shelter Area	50

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table XLIX)	Equivalent PF
A ₁	13
A ₂	18
A ₃	18

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>
1A	Roof of Fire Station	2,700	Tar & Gravel
18	Other Roofs	25,400	Tar & Gravel
2	Paved Parking	63,000	Asphalt
3	Streets	165,500	Asphalt
4	Lawns, Bare Earth, Fields, etc.	328,300	Grass & Bare Earth

E. Contribution to Intensity Factors (C_{1j} Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

- 1. Exterior walls brick and block (68 lb/ft²)
- 2. Roof 5" reinforces concrete (62 lb/ft²)

Table L lists the contribution to intensity factors of the various planes to the selected detector locations.

Table L CONTRIBUTION TO INTENSITY FACTORS (C $_{\mbox{i}\,\mbox{j}}$ VALUES) FOR FIRE STATION NO. 8

		De	tector Location j	
c	ontaminated Plane i	1 Equipment Storage Area	2 Alarm Switchboard	3 Shelter Area
1A	Roof of Fire Station	.0424	.0424	.0200
18	Other Roofs	. 0000	.0000	.0000
2	Paved Parking	.0011	.0009	.0000
3	Straets	. 1282	.0397	.0000
4	Grass & Ground	.0116	.0262	. 000υ

F. Relative Intensity Contributions (CF Values)

The relative intensity contributions are given in Table II below.

Table LI

RELATIVE INTENSITY CONTRIBUTIONS (CF values)

FOR FIRE STATION NO. 8

ĺ		Detector Location	٤
Contaminated Plane i	l Equipment Storage Area	2 Alarm Switchboard	3 Shelter Area
1A Roof of Fire Station	23	.39	1.00
1B Other Roofs	.00	.00	.00
2 Paved Parking	.01	.01	.00
3 Streets	. 70	.36	.00
4 Grass & Ground	.06	. 24	.00

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table LII

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR FIRE STATION NO. 8

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of Fire Station (1A)	.03	0.2	7
Grading	В	Ground (4)	. 10	79.2	1
Firehosing	С	Streets (3)	.03	11.5	7
Firehosing	D	Parking Lots (2)	.03	4.1	7

H. RN Values

The fraction of intensity remaining for selected strategies of decontamination is given in Table LIII below.

Table LIII

FRACTION OF INTENSITY REMAINING (RN, VALUES)

FOR SELECTED STRATEGIES FOR FIRE STATION NO. 8

		Detector Location j	
Combined Strategy	l Equipment Storage Area	2 Alarm Switchboard	3 Shelter Area
A	.76	. 62	.03
В	. 94	.78	1.00
С	. 32	. 65	1.00
D	.99	.99	1.00
A+B	. 72	. 41	.03
A+C	.10	.27	.03
B+C	.26	.43	1.00
A+B+C	. 94	. 05	.03
A+B+C+D	.03	.05	.03

I. RNA Values

The activity reduction factors for selected strategies and all activity patterns are given in Table LIV.

Table LIV

ACTIVITY REDUCTION FACTORS (RN VALUES) FOR SELECTED STRATEGIES AND ALL ACTIVITY PATTERNS FOR FIRE STATION NO. 8

	Activity Pattern		
Combined Strategy	A ₁	A ₂	A ₃
A	.65	. 52	.50
В	. 95	.89	. 83
С	.44	.63	. 72
D	1.00	.99	. 99
A+B	. 60	. 42	. 33
A+C	.09	.15	. 22
в+с	. 39	. 52	. 55
A+B+C	.04	.04	.05
A+B+C+D	.03	.04	.04

J. Conclusions

Tables LIII and LIV show that combined strategy A (firehosing roofs of fire station) B (grading the ground), and C (firehosing the streets) will reduce the radiation at any detector location or for any activity pattern to a maximum of 5% of its original value. Table LIII also shows that strategy D is, for all practical purposes, of no value.

Attention is brought to the wide variation of the contamination to the various detectors from the various planes, as shown in Table LI.

XI. DECONTAMINATION ANALYSIS OF RADIO STATION KXRX

A. Discussion

This small radio station is located just outside of the city of San Jose on a hill overlooking a highway. The station has an above ground fallout shelter attached to the main building. The station's ability to broadcast in a postattack situation could be vital as a means of informing the population of the state of the environment.

Figure 76 is a simplified diagram of the station showing the locations of the detectors and indicating the locations, sizes, and surface materials of contributing planes of contamination to the activity area. Figures 77 through 80 are a number of photographs taken around the area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 81 is a map showing the locations and directions of the photographs.

B. Definition of Activities

Four activity patterns are considered in this analysis. Four detector locations are used to characterize these activities. These detector locations are as follows:

Detector Location	Description
1	Broadcasting Studio
2	Engineering Room
3	Office
4	Fallout Shelter




Figure 76

A Map of the Area Around Radio Station KXRX Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 77

View 1 - Radio Station KXXX -A View of the Front of the Radio Station



Figure 78

View 2 - Radio Station KXRX - A View of the Station Transmission Towers and the Surrounding Area





figure 79

View 3 - Radio Station KXRX A View Showing the Fallout Shelter
Adjoining the Side of the Station



Figure 80

View 4 - Radio Station KXRX -A View Showing the Slopes of Ground from the Radio Station to the Freeway



A Map of the Area Around Radio Station KXRX Showing the Locations and Directions of the Photographs Shown in Figures 77 through 80

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each detector location. Thus, Table LV defines the four activity patterns.

FRACTION OF TIME AS REQUIRED BY ACTIVITY A
TO BE SPENT AT DETECTOR LOCATION
IN RADIO STATION KXRX

	Detector Location j			
Activity Pattern A _i	l Broadcasting Studio	2 Engineering Room	3 Office	4 Shelter Area
A ₁	.31	.00	.02	.67
A ₂	.00	.33	.00	. 67
A ₃	.18	.15	.00	. 67
A ₄	.00	.20	. 15	. 65

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 76)

De	etector Location	Original PF
1	Broadcasting Studio	1.4
2	Engineering Room	1.7
3	Office	1.7
4	Shelter Area	8.0

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table LV)	Equivalent PF
A ₁	3.2
Å ₂	3.6
A ₃	3.3
A ₄	3.5

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface Material
1A	Roof of KXRX	1,700	Asphalt Sheathing*
18	Other Roofs	****	••••
2	Paved Parking	10,100	Asphalt
3	Streets	71,700	Asphalt
4	Lawns, Bare Earth, Fields, etc.	701,500	Grass & Ground

E. Contribution to Intensity Factors (C Values)

The following gives the structural characteristics of the radio station which were required to calculate the contribution to intensity values.

1. Exterior walls

- a. Main building 2" timber planks (7 lb/ft²)
- b. Shelter area 8" cinder block (72 lb/ft²)

2. Roof

- a. Main building asphalt sheathing on timber (10 lb/ft²)
- b. Shelter area 6" reinforced concrete (75 lb/ft²)

^{*} Considered shingles for decontamination purposes.

Table LVI lists the contribution to intensity factors of the various planes to the selected detector locations.

		Detector Location j				
Contaminated Plane i		l Broadcasting Studio	2 Engineering Room	3 Office	4 Shelter Area	
1A	Roof of KXRX	. 1542	. 1545	. 1545	.0022	
1B	Other Roofs	.0000	.0000	.0000	. 0000	
2	Paved Parking	. 1863	.0821	. 2193	.0313	
3	Streets	.0011	.0007	.0014	.0000	
4	Grass & Ground	. 3656	. 3507	2105	.0920	

F. Relative Intensity Contributions (CF | Values)

The relative intensity contributions are given in Table LVII below.

Table LVLI

RELATIVE INTENSITY CONTRIBUTIONS (CF values)
FOR RADIO STATION KXPX

		Detector Location j				
	Contaminated Plane i	l Broadcasting Studio	2 Engineering Room	3 Office	4 Shelter Area	
lA	Roof of KXRX	. 22	. 26	. 26	.02	
18	Other Roofs	.00	.00	.00	.00	
2	Paved Parking	.26	.14	.37	. 25	
3	Streets	.90	.00	.00	.00	
4	Grass & Ground	.52	. 60	. 36	.73	

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table LVIII

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR RADIO STATION KXRY.

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof of KXRX (1A)	.05	0.1	6
Firehosing	В	Paved Parking (2)	.03	0.2	5
Vacuumized Sweeper	С	Streets (3)	.09	1.4	1
Grading	D	Ground (4)	.10	168.0	1

H. RN Values

The fraction of intensity remaining for selected strategies is given in Table LIX.

Table LIX

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES FOR RADIO STATION KXRX

	Detector Location j			
Combined Strategy	l Broadcasting Studio	2 Engineering Rcom	3 Office	4 Shelter Area
A	.79	. 75	.75	.98
В	.74	. 86	.64	.76
С	1.00	1.00	1.00	1.00
D	. 53	.46	. 68	.34
A+B+C	. 54	. 61	. 38	.74
A+B+D	. 07	.08	.06	.08

I. RN Values

The activity reduction factors for selected strategies and all the activity patterns are given in Table LX.

Table LX

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES

AND ALL ACTIVITY PATTERNS FOR RADIO STATION KXRX

Combined		Activity Patterns			
Strategy	A ₁	A ₂	A ₃	A ₄	
A	.84	. 82	.83	.82	
В	.74	. 83	.78	.76	
С	1.00	1.00	1.00	1.00	
D	.49	.43	.46	. 49	
A+B+C	.59	.65	. 62	. 58	
A+B+D	.07	.08	.08	.07	

J. Conclusions

Tables LIX and LX show that combined strategy A (firehosing the roof of the radio station), B (firehosing the paved parking), and D (grading the surrounding ground) reduces the fraction of intensity remaining at any detector location or for any activity pattern to a maximum of 8% of its original value. The most time consuming part of this decontamination process is grading the ground, which requires one man 168 hours to accomplish. The grading is necessary because the surrounding grass and ground offer over 50% of the relative intensity contribution to all detector locations except detector 3 (office).

It is interesting to note that, even though the radio station has an annex that is considered to be an above ground shelter, the calculated PF of this shelter is only 7.97

XII. DECONTAMINATION ANALYSIS OF OUTDOOR AREAS IN A RESIDENTIAL AREA

A. Discussion

In order to analyze the decontamination of outdoor areas in a residential area in San Jose, a typical surburan section was chosen. Detector locations (representing people) were placed outdoors in the center of a street and in a yard.

Figure 82 is a simplified diagram of the area chosen, showing the locations of the detectors and indicating the locations, sizes, and surface materials of contributing planes of contamination to the activity area. Figures 83 through 87 are a number of photographs of a typical residential area, showing some of the contaminated planes and other features of the area that would influence decontamination.

B. Definition of Activities

Two different activity patterns are considered in this analysis. Three detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Street
2	Yard
3	Shelter Area

١,




Figure 82

A Map of the Area Around Residential Area Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 83

View 1 - Residential Area -A View Showing a Typical Intersection



Figure 84

View 2 - Residential Area - A View Showing a Typical Street



Figure 85

View 3 - Residential Area -A View Showing a Typical Home



Figure 86

View 3 - Residential Area - A View Showing the Typical Closeness of the Homes




Figure 87

View 5 - Residential Area -A View Showing a Typical Shingle Roof

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table LXI defines the two activity patterns.

Table LXI

FRACTION OF TIME AS REQUIRED BY ACTIVITY A

TO BE SPENT AT DETECTOR LOCATION j

IN A RESIDENTIAL AREA

	Detector Location j				
Activity A_{j_i}	l Street	2 Yard	3 Shelter Area		
A ₁	.30	.00	.70		
A ₂	.00	.25	.75		

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 82)

Detector Locations	Original PF
l Street	1.6
2 Yard	1.8
3 Shelter Area	20

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern	(See Table LXI)	Equivalent PF
A ₁		4.4
A ₂		5.7

D. Contaminating Planes

Identification Number	Description	Area Size (in ft ²)	Surface Material
1A	Roof of Bldg.	None	
18	Roof of Other Bldgs.	150,000	Shingles
2	Paved Parking	None	*****
3	Streets	135,000	Asphalt
4	Lawns, Bare Earth, Fields, etc.	300,000	Grass and Bare Earth

E. Contribution to Intensity Factors (C Values)

Because the existance of a shelter area is assumed and the other two detector locations are outdoors, there were no building structural characteristics to be considered.

Table LXII lists the contribution to intensity of the various planes to the selected detector locations.

Table LXII

CONTRIBUTION TO INTENSITY FACTORS (C VALUES)

FOR A RESIDENTIAL AREA

Contaminated Plane i			Detector Location j		
		l Street	2 Yard	3 Shelter Area	
18	Roofs of Other Bldgs.	.0749	.1635	.0500	
2	Paved Parking	.0000	.0000	.0000	
3	Streets	.2264	.0195	.0000	
4	Grass & Ground	.3320	.3641	.0000	

F. Intensity Contributions (CF_{ij} Values)

The relative intensity contributions are given in Table LXIII below.

			Detector Location j		
	ntsminted Plane i	l Street	2 Yard	Shelter Area	
13	Roofs of Other Buildings	. 12	.30	1.00	
2	Paved Parking	.00	.00	.00	
3	Streets	. 36	.04	.00	
4	Grass a Ground	.52	.67	.00	

G. Cost and Effectiveness

Cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table LXIV

COST AND EFFFCTIVENESS DATA FOR SELECTED METHODS
OF DECONTAMINATING SURFACES FOR A RESIDENTIAL AREA

Method	Identi- fication Symbol	Surface (Surface	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Tesm Hours of Effort	No. in Team
Firehosing	A	Other Roofs (1B)	.05	5.0	ó
Firehosing	В	Streets (3)	. 03	1.8	5
Street Sweeper	С	Streets (3)	.06	2.7	1
Grading	D	Ground (4)	.10	72.0	1

H. RN Values

The fraction of intensity remaining for selected strategies is given in Table LXV below.

Table LXV

FRACTION OF INTENSITY REMAINING (RN, VALUES)

FOR SELECTED STRATEGIES FOR A RESIDENTIAL AREA

Combinea		Detector Location j	
Strategy	l Street	2 Yard	3 Shelter Area
A	. 89	.72	.05
В	.65	.97	1.00
e	. 66	.97	1.00
D	. 53	.40	1.00
A+B+D	.07	.08	.05
A+C+D	. 08	.08	.05

I. RN Values

The activity reduction factors for selected strategies and all activity patterns are given in Table LXVI.

Table LXVI

ACTIVITY REDUCTION FACTORS (RN VALUES)

FOR SELECTED STRATEGIES AND ALL ACTIVITY
PATTERNS FOR A RESIDENTIAL AREA

	Activity Pat	tern
Combined Strategy	A ₁	A ₂
A	.76	.57
В	.71	. 97
С	.72	.97
D	.60	.53
A+B+D	.07	.08
A+C+D	.08	.08

J. Conclusions

Table LXV shows that combined strategies A (firehosing roofs of houses), B (firehosing streets), and D (quading the ground) and A, D, and C (street sweeping the streets) are for all practical purposes equally efficient with respect to reducing radiation. Strategy C has the advantage that it requires only one man to work 2.7 hours while strategy B requires five men to work 1.8 hours. The most time consuming part of the decontamination process is grading the ground which requires one man to work 72 hours.

It is interesting to note that whether a man is considered to be in the street or in a yard the surrounding grass and ground contribute over 50% of the radiation he receives.

XIII. DECONTAMINATION ANALYSIS OF OUTDOOR LOCATIONS IN THE CENTRAL BUSINESS DISTRICT

A. Discussion

In order to analyze the decontamination of the central business district in San Jose, detector locations (representing people) were placed in two downtown outdoor areas. One of these detectors was placed in an intersection and another in a parking lot.


Figures 88 and 89 are simplified diagrams of central business areas, showing the locations of detectors and indicating the locations, sizes, and surface materials of some of the contributing planes of contamination to the various activity areas.

Figures 90 through 97 are a number of photographs showing typical downtown areas and some of the contaminated planes and other features that would influence decontamination.

B. Definition of Activities

Three different activity patterns are considered in this analysis. Three detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Intersection
2	Parking Lot
3	Shelter Area



A Map of the Area Around Main Intersection in San Jose Business District Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes




Figure 89

A Map of the Area Around a Section of the Business District Containing a Parking Lot in San Jose Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes




Figure 90

View 1 - Central Business District -A View Along South First Street



Figure 91

View 2 - Central Business District -A View Looking North on Market Street From the Corner of South Market and West Santa Clara Streets



Figure 92

View 3 - Central Business District A View of the Intersection of
2nd Street and Santa Clara



Figure 93

View 4 - Central Business District -A View Looking Down S. 1st Street



Figure 94

View 5 - Central Business District -A View Along S. 2nd Street



Figure 95

View 6 - Central Business District A View of the Intersection of W
Santa Clara and Market Streets




Figure 96

View 7 - Central Business District A View of the Intersection of
1st Street and Santa Clara




Figure 97

View 8 - Central Business District -A View Looking Lust Along W. Santa Clara Street The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table LXVII defines the three activity patterns.

Table LXVII

FRACTION OF TIME AS REQUIRED BY ACTIVITY A

TO BE SPENT AT DETECTOR LOCATION j in

THE CENTRAL BUSINESS DISTRICT

	Detector Location j		
Activity Pattern A	l Intersection	2 Perking Lot	3 Shelter Area
A ₁	.50	.00	. 50
A ₂	.33	.00	.67
^A 3	.00	.20	.80

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 88)

De	etector Location	Original PF
1	Intersection	1.7
2	Parking Lot	1.9
3	Shelter Area	100

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table LXVII)	Equivalent PF
^ 1	3.3
A ₂	4.8
A ₃	8.6

D. Contaminated Planes

1. Intersection

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>
1B	Roofs of Other Bldgs.	216,700	Tar & Gravel
2	Parking Lots	None	*****
3	Streets	164,800	Asphalt
4	Lawns, Bare Earth, Fields, etc.	None	*****

2. Parking Lot

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>
1B	Roofs of Other Bldgs.	113,600	Tar & Gravel
2	Parking Lots	17,300	Asphalt
3	Streets	16,200	Asphalt
4	Lawns, Bare Earth, Fields, etc.	None	•••••

E. Contribution to Intensity Factors (C Values)

Because the existance of a shelter area is assumed and the other two detector locations are outdoors, there were no building structural characteristics to be considered.

Table LXVIII lists the contribution to intensity factors for the various planes to the selected detector locations.

Table IXVIII

CONTRIBUTION TO INTENSITY FACTORS (C VALUES)

FOR CENTRAL BUSINESS DISTRICT

			Detector Location j		
-	taminated lane i	l Intersection	2 Parking Lot	3 Shelter Arca	
18	Roofs of Other Buildings	.0000	.0000	.0100	
2	Parking Lots	.0000	.5168	.0000	
3	Streets	.6059	.0226	.0000	
4	Grass & Ground	.0000	.0000	.0000	

F. Relative Intensity Contributions (CF Values)

The relative intensity contributions are given in Table LXIX below.

Table LXIX

RELATIVE INTENSITY CONTRIBUTIONS (CF_{ij} VALUES)

FOR CENTRAL BUSINESS DISTRICT

		Detector Location ;			
Contaminated Plane i		i Intersection	2 Parking Lot	3 Shelter Area	
18	Roofs of Other Buildings	.00	.00	1.00	
2	Parking Lots	.00	. જેઇ	.00	
3	Sireets	1.00	.04	.00	
4	Grass & Ground	.00	.00	.00	

G. Cost and Effectiveness

The cost and effectiveness data ic. selected methods of decontaminating surfaces are given in the following table. It was necessary to consider the intersection and parking lot separately because they are in two widely separated activity areas.

Table LXX

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR A CENTRAL BUSINESS DISTRICT

į.	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
		Detector î - Inter	section		
Firehosing	A	Streets (3)	.03	1.7	5
Street Sweeper	В	Streets (3)	.06	3.3	1
Vacumized Sweeper	С	Streets (3)	. 09	3.3	1
		Detector 2 - Parki	ng Lot		
Firehosing	D	Streets (3)	.03	0.2	5
Firehosing	٤	Paved Parking (2)	.03	0.2	5
Street Sweeper	F	Sireets (3)	.06	0.3	1
Street Sweeper	G	Paved Parking (2)	.66	0.4	1

H. RN Values

The fraction of intensity remaining for selected strategies is given in Table LXXI below.

Table LXXI

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES FOR CENTRAL BUSINESS DISTRICT

	Detector Location j				
Combined Strategy	1 Intersection	2 Parking Lot	3 Shelter Area		
A	.03		1.00		
В	.06		1.00		
c	.09		1.00		
n		.96	1.00		
E		.07	1.00		
7		.95	1.00		
G		. 10	1.00		
D+E		.03	1.00		
F+G		.06	1.00		

1. RA Values

The activity reduction factors for selected strategies and all activity patterns are given in Table LXXII.

Table LXXII

ACTIVITY REDUCTION (RNA VALUES) FOR SELECTED STRATEGIES

1D ALL ACTIVITY PATTERNS FOR SENTRAL SUSINESS DISTRICT

	Activity Pattern			
Combined Strategy	A ₁	A ₂	A ₃	
À	.05	.06		
В	.08	.09		
c	.10	.12		
p			. 26	
E			.13	
F			.96	
G			. 16	
D+E			. 10	
F+1:	<u> </u>		. 12	

J. Conclusions

At detector location 1 (intersection) the only contributing plane of contamination is the street. Table LXXI shows that the radiation intensity can be reduced to 3% of its original value by A (firehosing the streets), 6% of its original value by B (street sweeping the streets), or 9% of its original value by C (vacuumized sweeping the streets). The method of decontamination would depend upon the manpower and equipment available for performing the work.

At detector location 2 (parking lot) the paved parking contributes 96% of the relative intensity to the detector. Table LXXI shows the radiation intensity can be reduced to 7% of its original value by E (firehosing the parking lot) or 10% of its original value by G (street sweeping the parking lot). Again, the method of decontamination would depend upon the manpower and equipment available.

None of the methods of decontamination considered would reduce the radiation to the shelter area because the roof of the building containing the shelter is the only contributing plane of contamination. However, for any of the activity patterns considered the radiation is reduced to a maximum of 12% of its original value by the methods considered.

XIV. DECONTAMINATION ANALYSIS OF SAN JOSE CITY HALL

A. Discussion


San Jose City Hall is one of the complex of many city office buildings and other facilities. It is surrounded immediately by large areas for parking and open lawns.

Figure 98 is a simplified diagram of the building, showing the locations of detectors and indicating the locations, sizes, and surface materials of some of the contributing planes of contamination to the activity area. It also shows the three distinct wings into which the building is divided. Figures 99 through 104 are a number of photographs taken around the City Hall area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 105 is a map indicating the locations and directions of the photographs.

B. Definition of Activities

Four different activity patterns are considered in this analysis. Four detector locations are used to characterize the activity patterns. These detector locations are as follows:

Detector Location	Description
1	City Council Chambers
2	Mayor's Office
3	Public Works Department
4	Sassment Shelter Area



A Map of the Area Around San Jose City Hall Showing the Locations of Detectors and Indicating the Sizus, and Surface Materials of the Potentially Contributing Contaminated Planes




Figure 99

View 1 - San Jose City Hall A View of the End ...d Part
of the Front of the Building




Figure 100

View 2 - San Jose City Hall -Another View of the Front of the Building



Figure 101

View 3 - San Jose City Hall A View Showing Part of the Back
and Part of the Front of the Building




Figure 102

View 4 - San Jose City Hall -A View Showing the Back of City Hall and the Lawn



Figure 103

View 5 - San Jose City Hall -A View Showing the Front Entrance to the City Hall





Figure 104

View 6 - San Jose City Hall -A View Showing the Parking Area and Road Leading to the Side of the City Hall



A Map of the Area Around San Jose City Hall Showing the Locations and Directions of the Photographs Shown in Figures 99 through 104

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table LXXIII defines the four activity patterns.

Table LXXIII

FRACTION OF TIME AS REQUIRED BY ACTIVITY A

TO BE SPENT AT DETECTOR LOCATION j IN

SAN JOSE CITY HALL

	Detector Location j				
Activity Pattern	L City Council Chamber	2 Mayor's Office	3 Public Works Department	4 Bascment Shelter Area	
A ₁	.20	.10	.00	.70	
A ₂	.40	.00	.00	. 60	
A ₃	.00	. 35	.00	. 65	
A ₄	.00	.00	.33	.67	

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 98)

Detector Location	Original PF
l City Council Chambers	13
2 Mayor's Office	6.6
3 Public Works Department	5.7
4 Basement Shelter Area	1666

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table LXXIII)	Equivalent PF
A 1	33
A ₂	33
^ 3	19
A.4	17

D. Contaminated Planes

Identification Number	Description	Area Size	Surface Material
1.A	Roof of City Hall	29,600	Tar & Gravel
18	Other Roofs	155,800	Miscellaneous*
2	Paved Parking	205,500	Asphalt
3	Streets	348,000	Asphalt
4	Lawns, Bare Earth, Fields, etc.	341,000	Grass

E. Contribution to Intensity Factors (C_i Values)

The following gives the structural characteristics of the building which were required to calculate the contributuon to intensity values:

1. Part 1

a. Exterior Walls

- (1) Walls on north and south sides 3" glass (7 lb/ft²)
- (2) Wall on west side glass and brick (33 lb/ft²)
- (3) Wall on east side 12" brick (108 $1b/ft^2$)
- b. Floors 7" reinforced concrete (83 lb/ft²)
- c. Roof 5" reinforced concrete (63 lb/ft²)
- d. Interior walls 3/4" plywood sheathing (2 lb/ft²)

2. Part 2

a. Exterior Walls

- (1) Wall on east side glass and brick (30 lb/ft²)
- (2) Walls on south and west sides 10" brick (100 $1b/ft^2$)
- (3) Wall on north side included in section 1 of the building (0 1b/ft2)
- b. Floors 7" reinforced conciete (88 lb/ft²)
- c. Roof 5" reinforced concrete (63 lb/ft²)
- d. Interior walls 3/4" plywood sheathing (2 lb/ft²)

Considered tar and gravel for decontamination purposes.

3. Part 3

a. Exterior Walls

- (1) Walls on north and south side glass and brick (115 lb/ft²)
- (2) Walls on east and west side 12" brick (108 lb/ft²)
- b. Floors 7" reinforced concrete (88 lb/ft²)
- c. Roof 5" reinforced concrete (63 lb/ft²)
- d. Interior partition no partitions considered.

Table LXXIV lists the contribution to intensity factors of the various planes to the selected detector locations.

Table LXXIV

CONTRIBUTION TO INTENSITY FACTORS (Cij VALUES)

FOR SAN JOSE CITY HALL

	Detector Location j				
Contaminated Plane i	l City Council Chamber	2 Mayor's Office	3 Public Works Department	4 Basement Shelter Area	
1A Roof of City Hall	.0531	.0036	.0000	.0006	
1B Other Roofs	.0028	.0000	.0000	.0000	
2 Paved Parking	.0033	.0084	.0103	.0000	
3 Streets	.0059	.0277	.0159	.0000	
4 Grass & Ground	.0092	.1130	. 1491	.0000	

F. Relative Intensity Contributions (CF Values)

The relative intensity contributions are given in Table LXXV below.

Table LXXV

RELATIVE INTENSITY CONTRIBUTIONS (CF, VALUES)
FOR SAN JOSE CITY HALL

	Detector Location j				
Cont ami nated Plane i	l City Council Chamber	2 Mayor's Office	3 Public Works Department	4 Basement Shelter Area	
1A Roof of City Hall	.71	. 92	.00	1.00	
1B Other Roofs	.04	.00	.00	.00	
2 Paved Parking	.04	.06	.06	.00	
3 Streets	.08	. 18	.09	.00	
4 Grass & Ground	.12	.74	.85	.00	

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table LXXVI

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR SAN JOSE CITY HALL

Method	Identi- fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Tear
Firehosing	A	Roof (1A)	.03	2.3	7
Firehosing	В	Other Roofs (1B)	.03	11.1	7
Firehosing	C -	Paved Parking (2)	.03	2,2	5
Firehosing	D	Streets (3)	.03	2,4	5
Street Sweeper	E	Paved Parking (2)	.06	4.4	i
Street Sweeper	F	Streets (3)	.06	4.7	1
Grading	G	Ground (4)	.1	85.8	1

H. RN Vilues

The fraction of intensity remaining (RN, Values) for selected strategies of decontamination are given in Table LXXVII below.

Table LXXVII

FRACTION OF INTENSITY REMAINING (RN VALUES) FOR SELECTED STRATEGIES FOR SAN JOSE CITY HALL

		Detector Location j			
Combined Strategy	l City Council Chamber	2 Mayor's Office	3 Public Works Department	4 Basement Shelter Area	
A	.31	.98	1.00	.03	
С	.96	.95	.94	1.00	
D	.92	.82	.91	1.00	
E	.96	.95	.94	1.00	
F	.93	.83	.91	1.00	
G	.89	.33	.23	1.00	
A+B	.27	.98	1.00	.03	
A+B+C+D	.15	.75	.86	.03	
A+B+ E +F	.15	.75	.86	.03	
A+B+E+F+G	.04	.09	.09	.03	

I. RN. Values

The activity reduction factors for selected strategies and all activity patterns are given in Table LXXVIII.

Table LXXVIII

ACTIVITY REDUCTION (RN VALUES) FOR SELECTED

STRATEGIES AND ALL ACTIVITY PATTERNS
FOR SAN JOSE CITY HALL

	Activity Pattern				
Combined Strategy	A ₁	A ₂	A ₃	A ₄	
A	.64	.30	.97	.99	
С	.95	.96	.95	.94	
מ	.87	.92	.83	.91	
E	.95	.96	.95	.95	
F	.88	.93	.83	.92	
G	.61	.89	.34	.24	
A+B	.62	.27	.97	.99	
A+B+C+D	.45	.15	.74	.85	
A+B+E+F	.45	.15	.75	.85	
A+B+E+F+G	.07	.04	.09	.09	

J. Conclusions

Tables LXXVII and LXXVIII indicate that a combined strategy of A (firehosing the roof of the City Hall), B (firehosing the roofs of other buildings, E (street sweeping the parking lots), F (street sweeping the streets), and G (grading the surrounding ground) will reduce the radiation at any detector location or for any activity pattern to a maximum of 9% of its original value. Strategy B is an unnecessary part of the decontamination process, however, because Table LXXVII shows a combined strategy of A+B is of about the same value as strategy A along.

The most time consuming part of the decontamination is strategy G, which requires one man to grade ground for 85.80 hours.

Attention is brought to the fact that firehosing the parking lots and streets at a mass reduction factor level of .06 is, for practical purposes, as effective as using a level of .03, and it is less time consuming. This is true because the streets and paved parking offer a relatively small amount of the total radiation to the detector locations.

XV. DECONTAMINATION ANALYSIS OF VALLEY FAIR SHOPPING CENTER

A. Discussion

Valley Fair Shopping Center is located in an open area to the northwest of the intersection of Stevens Creek Road and a large freeway.

The shopping center consists of very closely knit structures, so that the whole complex, in effect, may be considered as one. Figure 106 is a simplified diagram of the shopping center, showing the locations of detectors, and indicating the locations, sizes, and surface materials of the contributing planes of contamination to the activity areas. Figures 107 through 114 are a number of photographs taken around the shopping center, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 115 is a map showing the locations and directions of the photographs.

B. Definition of Activities

Five different activity patterns are considered in this analysis. Three detector locations are used to determine these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Tunnel Area
2	Parking Lot #1
3	Parking Lot #2




Figure 106

A Map of the Area Around Valley Fair Shopping Center Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 107

View 1 - Valley Fair Shopping Center -A View of One of the Parking Areas



Figure 108

View 2 - Valley Fair Shopping Center -A View of Another Parking Area



Figure 109

View 3 - Valley Fair Shopping Center -A View of Part of the Roof of the Shopping Center and the Surrounding Area



Figure 110

View 4 - Valley Fair Shopping Center -Another View of the Roof of the Shopping Center and the Surrounding Area



Figure 111

View 5 - Valley Fair Shopping Center -A View from the Roof of Part of the Parking Area



Figure 1:2

View 6 - Valley Fair Shopping Center -A View of a Typical Covered Walkway in the Shopping Center



Figure 113

View 7 - Valley Fair Shopping Center A View of an Open Court in
the Shopping Center



Figure 11a

View 8 - Valley Fair Shopping Center -A View of an Open Walkway in the Shopping Center




Figure 115

A Map of the Area Around Valley Fair Shopping Center Showing the Locations and Directions of the Photographs Shown in Figures 107 through 114

These activities are described entirely according to the amount of time that an activity pattern requires a person to spend to each of the detector locations.

Thus, Table LXXIX defines the five activity patterns.

Table LXXIX

FRACTION OF TIME AS REQUIRED BY ACTIVITY A

TO BE SPENT AT DETECTOR LOCATION j

IN VALLEY FAIR SHOPPING CENTER

		Detector Location		
Activity Pattern A	1 Tunne1 Area	2 Parking Lot #1	3 Parking Lot #2	
A ₁	.60	.40	.00	
A ₂	1.00	.00	.00	
A 3	.70	.30	.00	
A _4	. 65	.00	.35	
A ₅	.70	.00	.30	

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 106)

Detector Location	Original PF
1 Tunnel Area	10,000
2 Parking Lot #1	2.2
3 Parking Lot #2	2.5

2. Equivalent Protection Factors for Activity Patterns

Activ	ity Pattern (See Taule LXXIX)	Equivalent PF
	A 1	5.5
-	A2	10,000
	^ 3	7.3
•	A ₄	7.1
	A ₅	8.3

D. Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface Material
1B	Other Roofs	323,900	Tar and Gravel
2	Paved Parking	959,700	Asphalt
3	Streets	316,800	Asphalt
4	Lawns, Bare Earth, Fields, etc.	350,600	Bare Earth and Gravel

E. Contribution to Intensity Factors

The following gives the structural characteristics of the tunnel area which were required to calculate the contribution to intensity values. (Because the detectors are outdoors at detector locations 2 and 3, there are no structural characteristics.)

Tunnel Area

- a. Exterior walls infinite ground
- b. Roof 6" reinforced concrete (75 lbs/ft 2).

Table LXXX lists the contribution to intensity factors of the various planes to the selected detector locations.

Table LXXX

CONTRIBUTION TO INTENSITY FACTORS (C values)
FOR VALLEY FAIR SHOPPING CENTER

		Datector Location j	
Contaminated Plane i	l Tunnel Area	2 Parking Lot #1	3 Parking Lot #2
1A Roof of Tunnel	.0001	.0000	.0000
15 Other Roofs	.0000	.0000	.0000
2 Parking Lots	,0000	.4347	. 3642
3 Streets	,0000	.0086	.0064
4 Crass & Ground	. 9 000	.0117	.0328

F. Relative Intensity Contributions

The relative intensity contributions are given in Table LXXXI balow.

Table LXXXI

RELATIVE INTENSITY CONTRIBUTIONS (CF values)

FOR VALLE FAIR SHOPPING CENTER

			Detector Location j					
Contaminated Plane i		1 Tunnel Area	Parking Lot #1	3 Parking Lot #2				
1.A	Roof of Bldg.	1.00	.00	.00				
18	Other Roofs	.00	.00	.00				
2	Parking Lots	.00	.96	.90				
3	Streets	.00	.02	.02				
4	Grass & Ground	.00	.03	.08				

G. Cost and Effectiveness

The cost and effectiveness data for selected method of decontaminating surfaces are given in the following table.

Table LXXXII

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS
OF DECONTAMINATING SURFACES FOR VALLEY FAIR
SHOPPING CENTER

Method	Identification Symbol	Surface (Surface Number)	Tass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Street Sweeper	A	Paved Parking (2)	.06	19.2	1
Firehosing	8	Paved Parking (2)	.03	9.6	5
Street Sweeper	С	Streets (3)	.06	6.4	1
Firehosing	D	Streets (3)	.03	3,2	3
Grading	E	Ground (4)	.10	34.0	1

H. RN Values

The fraction of intensity remaining for selected strategies of decontamination is given in Table LXXXIII below.

		Detector Locatio	n j
Combined Strategy_	1 Tunnel Area	2 Parking Lot #1	3 Parking Lot #2
A	1.00	.10	.15
В	1.00	.07	.12
С	1.00	.98	.99
מ	1.00	.98	.98
E	1.00	.98	.93
Λ+C	1.00	.08	.14
B+D	1.00	.05	.11
A+C+E	1.00	.06	.06
B+D+E	1.00	.03	.04

I. RN Values

The activity reduction factors for selected strategies and all activity patterns are given in Table LXXXIV.

Table LXXXIV

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED

STRATEGIES AND ALL ACTIVITY PATTERNS
FOR VALLEY FAIR SHOPPING CENTER

		Activity Pattern								
Combined Strategy	A ₁	A ₂	A ₃	A ₄	A ₅					
A	. 10	1.00	.10	.15	.15					
В	.07	1.00	.07	.12	.12					
С	.98	1.00	.98	.99	.99					
D	.98	1.00	.98	.98	. 98					
E	.98	1.00	.98	.93	.93					
A+C	.08	1.00	.08	.14	.14					
B+D	.06	1.00	.06	.11	.11					
A+C+E	.06	1.00	.06	.06	.06					
B+D+E	.03	1.00	.03	.04	.04					

J. Conclusions

No methods of decontamination were considered for the tunnel area, which could serve as a shelter area, because it has a calculated PF of 10,000.

The radiation at the two detector locations in the parking lots could be reduced to 10% of its original value by strategy A (street sweeping the paved parking) or 7% of its original value by E (firehosing the paved parking). Method A requires one man to work 19.2 hours while method B requires a team of five men to work 9.2 hours.


If it is felt necessary, a further alight reduction in radiation can be achieved by C (street sweeping the streets) or D (firehosing the streets). This is probably not worth the time and effort that would be expended.

XVI. DECONTAMINATION ANALYSIS OF SAN JOSE HOSPITAL

A. Discussion

San Jose Hospital is a large facility surrounded by parking lots, doctor's offices, and homes. It occupies an entire city block.

Figure 116 is a simplified diagram of the building, showing the locations of detectors and indicating the locations, sizes, and surface materials of the contributing planes of contamination to the activity area. It also shows the four wings into which the building is divided. Figures 117 through 124 are a number of photographs taken around the hospital area, showing some of the contaminated planes and other features of the area that would influence decontamination. Figure 125 is a map indicating the locations and directions of the photographs.



A Map of the Arka Around San Jose Hospital Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 117

View 1 - San Jose Hospital -A View Showing the Rear of the Hospital



Figure 118

View 2 - San Jose Hospital -A View of the Side of the Hospital Facing N. 14th Street



Figure 119

View 3 - San Jose Hospital *
A View Showing the Front
Entrance to the Hospital



Figure 120

View 4 - San Jose Hospital -A Partial View of the Interior Court of the Hospital



Figure 121

View 5 - San Jose Hospital -A View Along N. 15th Street



Figure 122

View 6 - San Jose Hospital -A View from the Top of the Hospital Showing the Surrounding Area




Figure 123

View 7 - San Jose Hospital -A View of the Hospital Roof





Figure 124

View 8 - San Jose Hospital -A View of the Hospital Parking Lot



A Map of the Area Around San Jose Hospital Showing the Locations and Directions of the Photographs Shown in Figures 117 through 124

B. Definition of Activities

Eleven different activity patterns are considered in this analysis. Twelve detector locations are used to characterize the activity patterns. These detector locations are as follows:

Detector Locations	Description
1	Operating Room (Ground Floor)
2	Central Medical Supply Area (Ground Floor)
3	Kitchen (Ground Floor)
4	Patient Room (1st Floor)
5	Admitting Office (1st Floor)
6	Nurse's Station (1st Floor)
7	Patient Room (2nd Floor)
8	Nurse's Station (2nd Floor)
9	Patient Room (3rd Floor)
10	Operating Room (3rd Floor)
11.	Nursery (3rd Floor)
1.2	Shelter Area (Basement)

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations. Thus, Table LXXXV defines the eleven activity patterns.

Table LXXXV

FRACTION OF TIME AS REQUIRED BY ACTIVITY $A_{\mathbf{i}}$ TO BE SPENT AT DETECTOR LOCATION j IN SAN JOSE HOSPITAL

	e G											
12	Shelter Area (Basemon	.65	09.	00.	.67	.65	8.	.67	.80	.65	89.	.65
11	Nursery (3rd F1.)	00.	œ.	1.00	9.	8.	00.	8.	00.	.10	8.	00.
10	Operating Room (3rd F1.)	00.	8.	90.	00.	01.	8.	8.	8.	.20	00.	0 0.
6	Room (3rd Fi.)	%	8.	8.	8.	.10	8.	8.	8.	50.	8.	8
ထ	Nurse's Station (2nd Fl.)	00.	8.	8.	œ.	.15	8.	8.	80.	8.	50.	8.
7	Patient Room (2nd Fl.)	00.	00.	%	00.	90.	%.	00	00	8.	.20	8.
9	Nurse's Station (1st F1.)	00.	00.	80.	00.	00.	00.	00.	.05	00.	00.	.15
5	Admitting Office (1st Fl.)	00.	00.	00.	%.	8.	%	.33	8.	00.	%.	ю.
ij	Patient Room (1st F1.)	.10	66.	ο.	00.	00.	1.00	8.	.10	8,	8.	.10
3	Kitchen (G.F.)	8.	00.	8.	.33	8.	8.	8.	8.	8	8.	ક્
2 Central	-	00.	07.	8.	8.	3.	8.	8.	50.	8.	.07	8.
_	Uperating Room (G.F.)	.25	8.	8.	8.	8.	8.	8.	8.	8.	8.	91.
	Activity Patteru A ₁	A1	× 2	۸,	7	* \$	۰ ۲	A,	~°	°~	A ₁₀	*
	1 3 4 5 6 7 8 9 10 11	Central Central Hedical Patient Admitting Nurse's Patient Room Station Room Station Room Room C.F.) (G.F.) (G.F.) (1st F1.) (1st F1.) (1st F1.) (1st F1.) (1st F1.) (3rd F1.) (3rd F1.) (3rd F1.) (3rd F1.)	Central Central Hedical Patient Admitting Nurse's Patient Nurse's Patient Room Room	Central Central Hedical Central Medical Patient Admitting Nurse's Patient Nurse's Patient Operating Nursery Room Roo	Central Central Hedical Central Muse's Patient Nurse's Patient Operating Nursery Room Room	Central Central Hedical Supply Patient Admitting Nurse's Ration Com Station Room Ro	Central Central Patient Admitting Nurse's Patient Nurse's Nursery Nursery Nurse's Nursery Nursery Nurse's Nurse's Nursery Nurse's Nurse's Nursery Nurse's Nurse's Nursery Nurse's Nu	Central Central Central Central Ce	Central Cent	Central Supple Patient Admitting Nurse's Room Station Supple Supple	Contral Contral Fatient Admitting Nurse's Fatient Room Roo	Cartail Cartail Patient Admitting Nurse's Patient Nurse's Nurse's Nurse's Patient Nurse's Nurs

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 116)

De	tector Location	Original PF
1	Operating Room (Ground Floor)	40
2	Central Medical Supply Area (Ground Floor)	250
3	Kitchen (Ground Floor)	357
4	Patient Room (1st Floor)	141
5	Admitting Office (1st Floor)	23
6	Nurse's Station (1st Floor)	24
7	Patient Room (2nd Floor)	79
8	Nurse's Station (2nd Floor)	42
9	Patient Room (3rd Floor)	69
10	Operating Room (3rd Floor)	12
11	Nursery (3rd Floor)	11
12	Shelter Area (Basement)	92

2. Equivalent Protection Factors for Activity Patterns

Activity Pattern (See Table LXXXV)	Equivalent PF
A ₁	71
A ₂ .	123
A ₃	11
A ₄	122
A ₅	49
A ₆	141
A ₇	47
^ 8	85
³ 9	30
^ 10	88
A ₁₁	60

D Contaminated Planes

Identification Number	Description	Area Size (in ft ²)	Surface <u>Material</u>
1 A	Roof of Hospital	33,600	Tar & Gravel
1 B	Other Roofs	119,000	Miscellaneous*
2	Paved Parking	141,900	Asphalt
3	Streets	278,600	Asphalt
4	Lawns, Bare Earth, Fields, etc.	2 9 9,800	Grass

E. Contribution to Intensity Factors (C_i Values)

The following gives the structural characteristics of the building which were required to calculate the contribution to intensity values:

1. Part 1

- a Exterior walls 8" cinder block (72 lb/ft²)
- b. Floors cellular steel deck and finishing (45 1b/ft²)
- c. Roof cellular steel deck and finishing (50 lb/ft²)
- d. Interior partitions 1" plaster on lath (10 1b/ft²)

2. Part 2

- a. Exterior walls 6" concrete block (48 lb/ft²)
- b. Floors cellular steel deck and finishing (45 1b/ft²)
- c. Roof cellular steel deck and finishing (50 lb/ft²)
- d. Interior partitions 6" concrete block (48 lb/ft²)

3. Part 3

- a. Exterior walls 6" concrete block (48 lb/ft²)
- b. Floors 4" reinforced concrete slab and finishing (60 lb/ft²)
- c. Roof asphalt covering on wooden planks (10 lb/ft²)
- d. Interior partitions 6" concrete block (48 lb/ft2)

^{*} Assumed tar and gravel for decontamination purposes.

4. Part 4

- a. Exterior walls 8" cinder block (72 lb/ft²)
- b. Floors cellular steel deck and finishing (45 lb/ft²)
- c. Roof cellular steel deck and finishing and tar and gravel (50 lb/ft²)

Table LXXXVI lists the contribution to intensity factors of the various planes to the selected detector locations.

F. Relative Intensity Contributions (CF, Values)

The relative intensity contributions are given in Table LXXXVII,

Table LXXXVI CONTRIBUTION TO INTENSITY FACTORS ($c_{i,j}$ values) for san jose hospital

						De	Detector Location j	ation j				
	_	2 Central		7	5	9	7	80	6	10	11	12
	Medical Operating Supply	Medical Supply		Patient	Admitting Nurse's	Nurse's	Patient	Nurse's	달	Operating		Shelter
Contaminated Plane i	(G. F.) (G.F.)	Area (C.F.)	Kitchen Room (G.F.) [(lst Fl		Office Station (.) (1st F1.) (1st F1.)	্	Room (2nd F1.)	Station (2nd F1.)	Room (3rd F1.)	Room (3rd F1.)	Nursery (3rd F1.)	Area (Bassment)
LA Roof of Hospital	.0120	.0012	2100.	.0014	.0410	.0018	0800.	.0126	0600.	.0767	.0767	0600.
18 Other Roofs	00 Co:	.0000	9000	.0020	6000	.0108	.0028	.0061	.0036	.0013	.0013	.000
2 Paved Parking	. wozs	.0013	7000 .	.0003	0000	.0017	.0003	.001	.0005	.0020	.0019	0000
) Streets	.0092	.0015	2100	.0014	9000	9600°	.0016	.0038	.0013	9100.	.0039	.0017
Crosse &	.001	9900.	0000	.0020	.0001	.0185	0000.	.0001	0000	.0001	.0032	.0002

Cyntaminated Flore 1	Operating Room (G,F.)	Centra! Medicai Supply Area (G.F.)	Kitchen (G.F.)	Patient Room (let Fl.)		Nurse's Station (1st Fl.)	Patient Room (2nd Fi.)	Nurse's Station (2nd Fl.)	Patient Room (3rd Fl.)	dmitting Nurse's Patient Nurse's Patient Operating Shelter Station Room Station Room Room Room Room Nursery Area (lst Fl.) (2nd Fl.) (2nd Fl.) (3rd Fl.) (3rd Fl.) (3rd Fl.) (3rd Fl.)	Mursery (3rd F1.)	Shelter Area (Masement)
LA Roof of Hospital	\$.	8.	.43	.20	96 .	\$.	.63	.53	.62	46.	88.	.83
18 Other Koofe	8	8.	8.	.28	.02	.25	.22	.26	.25	.02	10	8.
2 Paved Parking	. 11	.32	.14	ş	8,	7 0.	.02	.os	.03	.02	.02	8.
3 Streets	.37	.37	.43	.20	.01	.23	.13	.16	6.	.02	8.	.16
4 Crass & Cround	ş	8	8.	.28	96.	4.	8.	8.	8.	8.	\$.02

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table LXXXVIII

COST AND EFFECTIVENESS DATA FOR SELECTED METHODS OF DECONTAMINATING SURFACES FOR SAN JOSE HOSPITAL

Method	Identification Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roof (1A)	.07	1.5	7
Firehosing	В	Paved Parking	.03	1.4	5
Street Sweeper	С	Streets (3)	.06	5.6	1
Grading	D	Ground (4)	.10	72.0	1
Firehosing	E	Roof (1A)	.03	2.4	7
Firehosing	F	Roofs (1B)	.07	5.2	7

H. RN Values

The fraction of intensity remaining for selected strategies of decontamination is given in Table LXXXIX.

Table LXXXIX

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES FOR SAN JOSE HOSPITAL

						Detector Location	Location ;					
	_	2 Central	3	77	\$	9	Ç	æ	6	10	11	12
Combined Stratezy	Medica Operating Supply Room Area (G.P.) (G.F.)	Medical Supply Area (G.F.)	Kitchen (G.F.)	Patient Room (1st Fl.)	Admitting Office (1st Fl.)	Nurse's Station (1st Fl.)	Patient Room (2nd Fl.)	Nurse's Station (2nd Fl.)	Patient Room (3rd Fl.)	Operating Room (3rd Fl.)	Mursery (3rd Fl.)	Shelter Area
*	.56	.72	09.	.82	01.	96.	14.	.51	.42	.13	. 18	.23
95	60,	89.	98.	96:	1.00	96.	86.	.95	76.	86.	86.	1.00
ິບ	9 9.	.65	09.	.81	65.	62.	88.	.85	.92	8.	96.	.85
۵	9,5.	8.	1.00	27.	1.00	19.	1.00	3.00	1.00	1.00	76.	85.
ات	3 .	۲.	.58	.83	.07	96.	.39	87.	.39	60.	71.	.20
3.	8.1	8.1	1.00	.74	86.	92.	67.	92.	71.	66.	66.	1.00
***	95.	.72	09.	.55	60.	.72	.21	.27	.19	ıı.	.17	.23
•	57.	15.	97.	.78	.10	.92	.39	.46	.39	.10	.16	.23
A-B+C	01.	\$ 0.	90.	. 59	60.	.71	.27	.33	.30	80.	.12	60.
Decet.	8.	ş	%	. 58	.05	17.	.25	.29	.28	50.	80.	50.
B+C+D+E		ş	70.	.33	.05	.31	.25	.28	.28	20.	20.	70.

I. RN Values

The activity reduction factors for selected strategies and all activity patterns are given in Table XC.

Table XC

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED

STRATEGIES AND ALL ACTIVITY PATTERNS FOR SAN JOSE HOSPITAL

					Act	tivity	Pattern	s			
Combined Strategy	A ₁	A ₂	A ₃	A ₄	A ₅	A ₆	A ₇	A ₈	A ₉	A ₁₀	A ₁₁
A	.41	.33	. 18	.27	.25	.82	.15	.41	.17	.31	.58
В	. 95	.94	.98	.98	.98	.96	1.00	.99	.98	.98	.97
С	.76	.81	.96	.82	.91	.61	.94	.84	.95	.85	.80
D	.96	.99	.97	.99	.99	.75	.99	.90	.99	.99	.83
E	. 38	.30	.14	.24	.22	.81	.11	.38	.13	.28	.57
F	.9 9	1.00	.99	1.00	.94	.74	.99	.94	.98	.93	.90
A+F	. 39	.33	. 17	.27	.19	.55	.14	.35	.15	.24	.48
A+B	. 36	.27	.16	.26	.23	.78	.15	. 39	.15	.30	.55
A+B+C	. 12	.08	. 12	.08	.14	.59	.09	.23	.10	.15	.35
B+C+E	.09	.05	.08	.05	.11	.58	.05	.20	.06	.12	.33
B+C·+D+E	.05	.04	.05	.04	. 10	.33	.05	. 10	.05	.11	.16

J. Conclusions

It is interesting to observe from Table LXCXVII the differences in the relative intensity contributions to the various detectors from the contaminating planes.

Because of this wide variance, none of the combined decontamination strategies considered adequately reduced the radiation at all detector locations. If strategy F (firehosing the roofs of other buildings) were added to combined strategy B (firehosing the paved parking lots), C (street sweeping the streets), D (grading the

ground), and E (firehosing the roof of the hospital) the radiation could be substantially reduced for all detectors. Table LXXXIX shows that at <u>some</u> of the detector locations the radiation is reduced to an acceptable level by much simplier decontamination strategies than the one discussed above.

Only activity pattern A_6 has a relatively large amount, 33%, of the original radiation remaining after decontamination by strategy B+C+D+E. This is because A_6 requires a person to spend all of his time in a patient room on the first floor which receives 28% of all radiation from the roofs of other buildings. However, the original PF of the room was calculated to be 140.85.

Although detector 12 in the basement was chosen as the shelter area, its PF of 91.74 was somewhat lower than the PF's of the central medical supply area (250.00) and the kitchen (357.14) on the ground floor.

XVII. DECONTAMINATION ANALYSIS OF THE SEWAGE TREATMENT PLANT

A. Discussion

The Sewage Treatment Plant serves San Jose as well as nearby cities such as Santa Clara, etc. Due to this fact, its functioning is important, not only to the city of San Jose, but also to the southern San Francisco Bay Area. The plant is located outside the city limits on the north side of the city.

The complex consists of widely scattered buildings in a large open area (several hundred acres). The buildings are connected with each other by underground tunnels.

Figure 126 is an aerial view of the sewage plant facility. Figure 127 is a diagram of the facility, showing the locations of detectors and indicating the locations, sizes, and surface materials of the contributing planes of contamination to the activity area. The diagram also indicates the names of the various buildings. Figures 128 through 133 are a number of photographs taken in and around the facility, showing some of the contaminated planes and other features that would influence decontamination. Figure 134 is a map showing the locations and directions of the photographs.





Figure 126 Aerial View of the Sewage Treatment Plant Facility



A Map of the Area Around Sewage Treatment Plant Showing the Locations of Detectors and Indicating the Sizes, and Surface Materials of the Potentially Contributing Contaminated Planes



Figure 128

View 1 - Sewage Treatment Plant A View of the Central Control Building and
the Adjacent Parking Lot



Figure 129

View 2 - Sewage Treatment Plant A View of the Central Control Building and
the Surrounding Area




Figure 130

View 3 - Sewage Treatment Plant A View of the Control Panel in the
Central Control Building



Figure 131

View 4 - Sewage Treatment Plant -A View of the Pump Well in the Central Control Building





Figure 132

View 5 - Sewage Treatment Plant A View of an Underground Tunnel Leading
from the Central Control Building



Figure 133

View 6 - Sewage Treatment Plant A View of a Fallout Shelter Area in the
Central Control Building



A Map of the Area Around Sewage Treatment Plant Showing the Locations and Directions of the Photographs Shown in Figures 128 through 133

Figure 134

B. Definition of Activities

Five different activity patterns were considered in this analysis. Five detector locations are used to characterize these activity patterns. These detector locations are as follows:

Detector Location	Description
1	Laboratory
2	Central Control Instrumentation Panel (Second Story)
3	Pump Room (First Floor)
4	Outdoor Area
5	Shelter Area

The activities are described entirely according to the amount of time that an activity pattern requires a person to spend at each of the detector locations.

Thus, Table XCI describes the five activity patterns.

Table XCI

FRACTION OF TIME AS REQUIRED BY ACTIVITY A₄ TO BE SPENT AT DETECTOR LOCATION j IN THE SEWAGE TREATMENT PLANT

:		Detector 1	ocation j		
Activity Pattern A _i	l Laboratory	Central Control Instrumenta- tion Panel	3 Pump Room	4 Outdoor Area	5 Shelter Area
A ₁	.30	.00	.00	.00	.70
A ₂	.00	.25	.00	.10	.65
A ₃	.00	.30	.05	.00	.65
A4	.00	.10	.20	.00	.70
A ₅	.10	.20	.00	.05	.65

C. Protection Factors

1. Original PF's at Detector Locations (See Figure 116)

	Detector Location	Original PF
1	Laboratory	9.2
2	Central Control Instrumentation Panel	9.4
3	Pump Room	16
4	Outdoor Area	1.5
5	Shelter Area	2000

2. Equivalent Protection Factors for the Activity Patterns

Activity Pattern (See Table XCI)	Equivalent PF
A ₁	30
A ₂	11
A ₃	28
A ₄	43
A ₅	15

D. Contaminated Planes

Identification Number	Description	Area Size	Surface <u>Material</u>
î A	Roofs of Central Control and Administration and Laboratory Buildings	27,600	Tar and Gravel
1 B	Other Roofs	37,300	Tar and Gravel
2	Paved Parking	43,200	Asphalt
3	Streets	95,300	Asphalt
4	Lawn, Bare Earth, etc.	1,557,800	Grass and Bare Earth

E. Contribution to Intensity Factors (C1 Values)

The following gives the structural characteristics of the buildings which were required to calculate the contribution to intensity values:

- 1. Administration and Laboratory Building
 - a. Exterior Walls 9" cinder block (80 lbs/ft²)
 - b. Roof 6" reinforced concrete (75 lbs/ft²)
- 2. Central Control Building
 - a. Exterior Walls
 - (1) First story 13" cinder block (120 lbs/ft²)
 - (2) Second Story 9" cinder block (80 lbs/ft²)
 - b. Floor 6" reinforced concrete (75 lbs/ft?)
 - c. Roof 6" reinforced concrete (75 lbs/ft²)

Table XCII lists the contribution to intensity factors of the various planes to the selected detector locations.

			Detector Loca	ation j		
Co	ontaminated Plane i	l Laboratory	2 Central Control Instrumen- tation Panel	3 Pump Room	4 Outdoor Area	5 Shelter Area
1A	Roof of Building	,0380	.0406	.0058	.0000	.0005
18	Other Roofs	.0000	.0000	.0000	.0000	.0000
2	Paved Parking	.0028	.0024	.0018	.0130	.0000
3	Streets	.0006	.0008	.0006	.0104	.0000
4	Grass and Grounds	0675	0632	.0522	65/19	_0000

F. Relative Intensity Contributions (CF_{ij} Values)

The relative intensity contributions at detector location j from contaminated plane i are given in Table XCIII below.

Table XCIII

RELATIVE INTENSITY CONTRIBUTIONS (CF_{ij} VALUES) FOR THE SEWAGE TREATMENT PLANT

Contaminated Plane i		Detector Location j						
		1 Laboratory	Central Control Instrumenta- tion Pane!	3 Pump Room	4 Outdoor Area	5 Shelter Area		
1A	Roof of Central Control or Labora- tory and Adminis- tration Building	.35	.38	.10	.00	1.00		
1B	Other Roofs	.00	.00	.00	.00	.00		
2	Paved Parking	.03	.02	. ავ	.02	.00		
3	Streets	.01	01	.01	.02	.00		
4	Grass and Ground	.52	.59	.86	.97	.00		

G. Cost and Effectiveness

The cost and effectiveness data for selected methods of decontaminating surfaces are given in the following table.

Table XCIV

COST AND EFFECTIVENESS DATA FOR SELECTED STRATEGIES OF DECONTAMINATING SURFACES FOR SEWAGE TREATMENT PLANT

Method	Identi fication Symbol	Surface (Surface Number)	Mass Reduction Factor (Fraction fallout material remaining after decontamination)	Team Hours of Effort	No. in Team
Firehosing	A	Roofs of Central Control, Laboratory & and Adminis- tration Buildings (1A)	.03	2.0	7
Firehosing	B	Paved Parking (2)	.03	0.4	5
Grading	С	Grees and Ground (4)	.10	374.0	<u> </u>

H. RN; Values

The fraction of intensity remaining for selected strategies is given in Table XCV below.

Table XCV

FRACTION OF INTENSITY REMAINING (RN, VALUES) FOR SELECTED STRATEGIES
FOR THE SEWAGE TREATMENT PLANT

	Detector Location j							
Combined Strategy	1 Laboratory	2 Central Control Instrumenta- tion Panel	Pump Room	4 Outdoor Area	5 Shelte: Area			
A	.66	.63	.91	1,00	.03			
\$.98	. 98	.97	.98	1.00			
C	. 44	.47	, 22	.13	1,00			
ል ተ ል	.64	.61	.88.	. 98	.03			
A+C	.10	.10	.13	.13	.03			
A+B+C	.08	08	10	- 11	.03			

I. RNA Values

The activity reduction factors for selected strategies and all activity patterns are given in Table XCVI.

Table XCVI

ACTIVITY REDUCTION FACTORS (RNA VALUES) FOR SELECTED STRATEGIES AND ALL.

ACTIVITY PATTERNS FOR THE SEWAGE TREATMENT PLANT

Combined	Activity Pattern					
Strategy	A ₁	A ₂	А3	A ₄	A ₅	
A	.65	.89	.65	.77	.82	
В	.98	.98	. 98	.97	. 98	
С	.45	.23	.45	.35	.29	
A+B	.63	.87	.63	.74	.80	
A+C	.10	.12	.10	.11	.12	
A+B+C	.08	.10	.08	.09	.10	

J. Conclusions

The tunnels connecting the buildings at the Sewage treatment facility offer the largest single available shelter area to the s. recounding area. However, they were not considered in this decontamination analysis because the tunnels are underground and have an extremely high PF. Therefore, decontamination is unnecessary with respect to detectors or activities taking place in these shelters.

For the detector locations considered, Table XCV shows that combined strategy A (firehosing the roofs of the Central Control and Administration and Laboratory Buildings), B (firehosing paved parking), and C (grading the surrounding grass and ground) leaves a maximum of 11% of the original radiation at any detector location. If a maximum of 13% of the original radiation is acceptable, combined strategy A+C is sufficient.

The most time consuming part of either of the above combined strategies is method C, which requires one man to work approximately 374 hours grading. Grading the ground is necessary because the ground contributes a minimum of 59% of the total radiation to all detectors except the shelter area.

XVIII. SUMMARY AND CONCLUSIONS

In the decontamination analyses reported in this paper, the roofs of most of the facilities offered the major portion of the relative intensity at the various detector locations within the facilities. In all cases, for adequate reduction in radiation (reduction by at least a factor of 5) it was necessary to decontaminate at least the roof of the building under consideration. In fact, for facilities well shielded by structures with roofs higher than the detectors selected, decontaminating the roof alone provided sufficient radiation reduction. The analysis showed further that roof decontamination provided more usable space with regard to effort expended than decontamination of any other plane. Table XCVII, extracted from the relative intensity contribution tables of the facilities analyzed, illustrates the importance of the roof contribution.

Table XCVII

FRACTION OF TOTAL INTENSITY TO VARIOUS DETECTOR LOCATIONS
CONTRIBUTED BY THE ROOF OF THE FACILITY

	T	Fraction
		of Intensity
'	Detector	Contributed by
Facility	No. and Description	the Roof
California Packing Corp.		
Plant No. 51	l Dried Fruit Grading Area	. 94
Tialit No. 31	3 Fruit Bins	.96
	5 Store Room	.95
	6 Work Shop	.91
	7 Shipping Department	.89
	8 Shelter Area	1.00
California Pharmaceutical		
Company	1 Laboratory	.24
Pacific Telephone and		
Telegraph Co.	1 Long Distance Switchboard	.94
Telegraph Co.	2 Information Switchboard	.92
	3 Automatic Exchange	.71
	Equipment Room	.72
	Equipment Room	.12
Dole Corp. Warehouse	2 Area A in Warehouse	.91
•	4 Area C in Warehouse	.90
San Jose Mercury-News	1 Truck Loading Dock	.62
San Jose Mercury-News	3 Copy Room	.98
	4 Type Setting Room	.65
	, ,	
Western Greyhound Bus		
Lines Depot	1 Ticket Counter	.55
	2 Baggage Room	. 55
	3 Main Lobby	.53
San Jose City Lines	l Repair Area A	.73
	3 Repair Area C	.70
Cinn Com Vond	1 Food-was Grander Budlidge	. 47
City Corp. Yard	l Equipment Storage Building 2 Electrical Shop	.74
	2 Electrical Shop 4 Machine Shop	.74
Fire Station No. 8	l Equipment Storage Area	.23
	2 Alarm Switchboard	. 39
Radio Station KXRX	l Broadcasting Studio	.22
	3 Office	.26
San Jose City Pall	1 City Council Chamber	.71
San Jose Hospital	i Operating Room (G.F.)	.48
and the stand to the stand of t	2 Central Medical Supply Area	. 30
	3 Kitchen (G.F.)	.43
	5 Admitting Office (let Floor)	.96
•	7 Patient Room (2nd Floor)	.63
	9 Patient Room (3rd Floor)	. 62
	10 Operating Room (3rd Floor)	.94
	11 Nursery (3rd Floor)	. 88
	12 Shelter Area (Basement)	.83
Carrag Traspunse Wines	Lishanstory	. 35
Sawage Trantment Plant	l Leboratory 2 Central Control Instruction	_
	* Central Control Instruction	

High velocity firehosing is one of the most efficient methods of decontaminating roofs. Assuming manpower, equipment, and water under sufficient pressure are readily available (which would seem to be the general case), it is also a rapid method of decontamination. In firehosing very large or very high roofs, consideration should be given to the length of hose runs that are necessary.

Paved areas, such as streets and parking lots, may be decontaminated by wet (firehosing and motorized flushers,) or dry (street sweepers and vacuumized sweepers) methods. If mechanized methods are available, they are preferable to firehosing because of their higher efficiency. In particular, firehosing of large paved areas could, generally, present a drainage problem.

If paved streets and parking lots are adjacent to or very near the sites and facilities analyzed, they contribute a greater fraction of the total intensity at the detector locations, and become of more significance in decontamination strategies. However, none of the areas involved (including the shopping center parking lots) were large enough to make decontamination prohibative.

In decontaminating roofs and paved surfaces, the method of decontamination and the mass reduction factor selected become more important as the relative intensity contribution (i.e., the fraction of the total intensity) of the plane under consideration becomes greater. In other words, as the relative intensity contribution decreases, the choice of decontamination method can more heavily depend upon the readily available equipment and manpower with little difference in effectiveness.

If facilities are adjacent to or surrounded by large areas of grass or bare earth, grading or bulldozing becomes an important decontamination strategy. This method was found to be the most time consuming part of any combined decontamination strategy which included it. Considerable judgment should be exercised in determining the necessity for decontaminating a facility or site which requires a large amount of grading.

Three generalizations derived from this study are: (1) as a building becomes

larger or the detector locations are subject to widely varying relative intensity contributions from various planes, decontamination strategies become more complicated, costly, and time consuming; (2) the less shielding afforded a building by surrounding structures the greater must be the area involved in the decontamination strategy; and (3) roof decontamination appears to be a useful strategy more often than any other "simple-plane" decontamination strategy.

REFERENCES

- 1. J. T. Ryan. <u>Initial Considerations for an Analysis of Decontamination</u>
 <u>Effectiveness in Municipal Areas</u>. RM-OU-214-1. Durham, North Carolina:
 Research Triangle Institute, Operations Research and Economics Division,
 April 1, 1965.
- 2. E. L. Hill, T. Johnson, and R. O. Lyday, Jr. <u>Computer Program for Analysis of Building Protection Factors Parts I and II</u>. RM-205-1. Durham, North Carolina: Research Triangle Institute, Operations Research and Economics, July 6, 1965.
- 3. C. Dillard and J. Ryan. A Fortran Program for Decontamination Analysis. RM-OU-214-10. Durham, North Carolina: Research Triangle Institute, Operations Research and Economics Division, August 31, 1965.

Security Classification

DOCUMENT CO (Security classification of title, body of abstract and indexis	NTROL DATA - R&		the ovurall report is classified)	
1 ORIGINATING ACTIVITY (Corporate author)			RT SECURITY C LASSIFICATION	
Research Triangle Institute			NCLASSIFIED	
Post Office Box 490		26 GROUI	· · · · · · · · · · · · · · · · · · ·	
Durham, North Carolina 27702	:	IS GROOM		
3 REPORT TITLE		L		
Radiological Recovery Requirements, St	ructures, and	Operatio	ons Research -	
Volume III - Decontamination Analysis				
San Jose, California				
4 DESCRIPTIVE NOTES (Type of report and inclusive dates)				
Volume III of a 4-volume final report:	19 February	1965 - (6 June 1966	
5 AUTHOR(S) (Last name, first name, initial)				
Walker, Sylvia M.				
REPORT DATE 74. TOTAL NO. OF 1		AGES	75. NO. OF REFS	
6 June 1966	221		3	
BA CONTRACT OR GRANT NO.	94 ORIGINATOR'S RE	PORT NUM	BER(S)	
N228(62479)-68153	R-0U-214			
b PROJECT NO.				
OCO Work Unit No. 3233B				
c	96. OTHER REPORT	VC(S) (Any	other numbers that may be sasigned	
RTI Project OU-214	this report)	•		
d	Volume	III		
10 AVAILABILITY/LIMITATION NOTICES		· · · · · · · · · · · · · · · · · · ·		
Distribution of this document is unlin	nited.			
11 SUPPLEMENTARY NOTES	12. SPONSORING MILIT	TARY ACT	VITY	
None	Office of Civil Defense			
1-VAC	Department of the Army			
	Washington.	D. C.	20310	
13 ABSTRACT				

This is Volume III of four separately bound volumes that report the research completed under the general terms of the Office of Civil Defense Subtask No. 3233B, "Radiological Recovery Requirements, Structures, and Operations Research". This volume contains the supporting data related to decontamination analysis of sixteen sites and facilities from San Jose, California. Volume I describes the general aspects of the investigations and presents the conclusions and recommendations.

KEY WORDS		LINK A		LINK B		LINK C	
KET WORDS		ROLE	WT	ROLE	WT	ROLE	WT
Operations Research		10	4				
Decontamination						8	4
Recovery						2	4
Radioactive Fallout				9	3		
Postattack Operation						10	3
Contamination				5	3		
Radiological Contamination				5	3		
Radiation Hazards				1	3		
Dose Rate				6	2		
Cleaning						10	2
Structures	Tarak	9	2				
Protection Factor	,	6	1				
Civil Defense System						0	1
<u>-</u>							
					<u> </u>	l	

INSTRUCTIONS

- 1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of Defense activity or other organization (corporate author) issuing the report.
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overall security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordance with appropriate security regulations.
- 2b. GROUP: Automatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manuel. Enter the group number. Also, when applicable, show that optional narkings have been used for Group 3 and Group 4 as authorized.
- 3. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cannot be selected without classification, show title classification in all capitals in parenthesis immediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is covered.
- 5. AUTHOR(S): Enter the name(s) of author(s) as shown on or in the report. Enter last name, first name, middle initial. If military, show rank and branch of service. The name of the principal author is an absolute minimum requirement.
- 6. REPORT DATE: Enter the date of the report as day, month, year; or month, year. If more than one date appears on the report, use date of publication.
- 7a. TOTAL NUMBER OF PAGES: The total page count should follow normal pagination procedures, i.e., enter the number of pages containing information.
- 7b. NUMBER OF REFERENCES. Enter the total number of references cited in the report.
- 3a. CONTRACT OR GRANT NUMBER: If appropriate, enter the applicable number of the contract or grant under which the report was written.
- 8b, 8c, & 8d. PROJECT NUMBER: Enter the appropriate military department identification, such as project number, subproject number, system numbers, task number, etc.
- 9a. ORIGINATOR'S REPORT NUMBER(S): Enter the official report number by which the document will be identified and controlled by the originating activity. This number must be unique to this report.
- 9b. OTHER REPORT NUMBER(S): If the report has been assigned any other report numbers (either by the originator or by the sponsor), also enter this number(s).

- 10. AVAILABILITY/LIMITATION NOTICES: Enter any limitations on further dissemination of the report, other than those imposed by security classification, using standard statements such as:
 - (1) "Qualified requesters may obtain copies of this report from DDC."
 - (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
 - (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
 - (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified users shall request through
 - (5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the report has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if known.

- 11. SUPPLEMENTARY NOTES: Use for additional explanatory notes.
- 12. SPONSORING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.
- 13. ABSTRACT: Enter an abstract giving a brief and factual summary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical report. If additional space is required, a continuation sheet shall be attached.

It is highly desirable that the abstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (TS), (S). (C), or (U).

There is no limitation on the length of the abstract. However, the suggested length is from 150 to 225 words.

14. KEY WORDS: Key words are technically meaningful terms or short phrases that characterize a report and may be used as index entries for cataloging the report. Key words must be selected so that no security classification is required. Idenfiers, such as equipment model designation, trade name, military project code name, geographic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, rules, and weights is optional.